FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	**CLAIM STATUS**	Authorized
MYERS RV CENTER INC		**CLAIM**	2636079
12024 CENTRAL AVE S.E.		**CLAIM ORIGIN**	WEB
ALBUQUERQUE, NM 87123		**ORIGINAL CLAIM ID**	
USA		**VIN**	5ZT2RPJC1RV025973
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	$190.00	**SITE/WAREHOUSE**	047 / 047D
OWNER INFORMATION		**ITEM #**	RPT196-47
CHRISTOPHER HUMPHREYS		**DEALER RO #**	73140
509 DOE LN SE		**CLAIM START DATE**	04/09/2026
Albuquerque, NM 87123		**CLAIM END DATE**	01/01/1900
USA			
Retail Date of Purchase	05/29/2025	**WARRANTY EXPIRATION DATE**	05/29/2026

Claim Line Details

Labor

Line# 1

Operation Code 60-138-24-00-001535

Operational Description Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-09 09:38:36 :: Complaint: Customer states when using black water flush, water comes out from under the unit. Under where the black tank flush is and other side under where the waste water holding tank is. Cause: Filled up black tank all the way until standing water is in toilet. Filling up gray tank currently to check for leaks. Determined that the shower is leaking at the drain, underneath the shower. Upon taking it to be dumped, a bunch of water built up in the underbelly padding from the leaking shower. Correction: Need to repair the leak under the shower at the drain

Model#		**Dlr Sub Hrs**	1.50	**Sub Labor Amt**	$285.00
Serial#		**Appr Hrs**	1.00	**Appr Labor Amt**	$190.00

Notes

excessive time requested. Time reduced based on photos, description and flat rate.
-Authorized - Repair as stated

Labor

Line# 2

Operation Code 60-138-01-00-001537

Operational Description Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-09 09:40:58 :: Complaint: When using black water flush, water also comes out from one of the walls inside the unit, kind of where the wall begins to go around, may be coming out of toilet area Cause: Found that the issue was being caused by the back flow preventer check valve for the black tank flush leaking profusely Correction: Replace check valve

Model#		**Dlr Sub Hrs**	0.50	**Sub Labor Amt**	$95.00
Serial#		**Appr Hrs**	0.35	**Appr Labor Amt**	$66.50

Notes

excessive time requested. Time reduced based on photos, description and flat rate.
-Authorized - Replace as Stated

Labor

Line# 3

Operation Code 30-100-02-00-003062

Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-09 09:43:48 :: Complaint: Cabinet door above kitchen sink is broke, hinge broke off door Cause: Issue caused by the bouncing of the trailer which had caused the screw holes to strip Correction: Recommend moving the piston to the other side of the door using proper screws to secure

Model#		**Dlr Sub Hrs**	0.25	**Sub Labor Amt**	$47.50
Serial#		**Appr Hrs**	0.15	**Appr Labor Amt**	$28.50

Notes
excessive time requested. Time reduced based on photos, description and flat rate.
-Authorized - repair as stated

Labor

Line# 4

Operation Code	Operational Description
50-134-01-00-001443	LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-04-09 09:46:54 :: Complaint: Refer is not staying cold on LP, works when on shore power Cause: When first attempting to start it up in propane mode, there was a red light indicating that propane mode was not working, but then it started after attempting a second lighting of the pilot. Ignite fridge and start cooling from a different line. Determined that the regulator needs to be replaced. Correction: Replace regulator and verify it is working after replacing.

Model#		**Dlr Sub Hrs**	0.50	**Sub Labor Amt**	$95.00
Serial#		**Appr Hrs**	0.50	**Appr Labor Amt**	$95.00

Notes

Labor

Line# 5

Operation Code	Operational Description
70-472-01-00-003341	Suburban Elite Griddle Regulator - Appliances/Cooktop/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-04-09 09:47:45 :: Complaint: Stove top burners are not staying light Cause: Regulator is running at 9 and it needs to be 11 Correction: Regulator needs to be replaced on the unit

Model#	3DN2U	**Dlr Sub Hrs**	0.50	**Sub Labor Amt**	$95.00
Serial#	213904384Y	**Appr Hrs**	0.50	**Appr Labor Amt**	$95.00

Notes
Hello, this message is to alert you that Forest River is currently reviewing your request with the vendor. The contract on the claim has been included in the email to the vendor. Also please refrain from submitting an order for this repair until the authorization is complete. Please be sure to read the feedback notes upon receiving authorization for additional details. We will update the line once we receive their response. Thank you
The vendor has reviewed this repair, and the line has been authorized at .5 hr according to their response and flat rate schedule. Thank you

---

Submitted		
	Labor Amt	$617.50
	Parts & Freight	$0.00
	Total	$617.50

Approved		
	Labor Amt	$475.00
	Parts & Freight	$0.00
	Total	$475.00

DEALER SIGNATURE **DATE**
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**
All repairs described have been inspected and are satisfactory.