MYERS RV CENTER
SALES ★ PARTS ★ SERVICE

12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73090-2
Promised Date:

WO #: 73090-2
Customer Name: 1000 - MYERS "RV" CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9689 2026 TRACER 275BH
Serial#: 527080
Chassis#: 5ZT2TRTB4TB527080
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 16 JUN 26
Time In:

Job #01 - Warranty
COMPLAINT: Wire short for awning / Awning electrical short

CAUSE: On the switch leg to the awning which is yellow and white, the white wire was shorted to ground. The supply power to the awning and lights which is a black wire at 8.3 V at the switch.

CORRECTION: Pulled the switch panel off of the wall tested for power and ground of the awning switch. I had 8 V at the switch and had a good ground. Tested the switch for proper function and it does function properly. Disconnected the switch leg to the awning which is yellow and white. Found the white wire has a short to ground. I pulled on the yellow and white wire that comes through the ceiling and I was able to free up about 6 inches and the short in the white wire went away. My guess it was just a staple and I pulled the staple out. There is no more short Im not going to run a new wire at this time however if this issue comes back I will have to run a new wire from the switch panel down to the awning. As far as the low-voltage goes the black and white wire runs across the bottom of the cabinet in the kitchen so we pulled the two lights tested for good connection to make sure there is no voltage drop through the lights didnt see any bad connections. The fuse panel has proper output voltage. We pulled the fuse panel to see where that wire runs and it runs behind the refrigerator. Had to pull the refrigerator to find out whats back there. I had a good voltage before the refrigerator and bad voltage behind the refrigerator. After removing the refrigerator we found a section of wire that had been stripped and some wires that had been kinked.So we cut out the defective area and reconnected with butt connectors. Tested for proper voltage at the switch panel voltage was correct. All the lights inside and the awning is working now as it should. Refrigerator it had to be reinstalled two lights had to be reinstalled switch panel I had to be reinstalled connections at the awning had to be remade and resealed. Job completed requesting 3 hrs and 45 mins for repair

Labor

Job #	Description	Total
01	Wire short for awning(WARRANTY)	N/C

Parts

Part #	Description	Qty	Price	Total
1703	ATC-15 FUSE	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #01: 0.00

Job #02 - Warranty
COMPLAINT: DAMAGE TO SLIDE FACIA OVER COUCH

CAUSE: Slide top fascia damaged during transport

Customer #: 1000
MYERS "RV" CENTER, INC.,

© 2026 Integrated Dealer Systems

CORRECTION: Need to order and replace slide fascia top . Requesting 45 mins for removal of old fascia and install of new fascia .need to remove screws secure if fascia to slide out itself .once screws are removed need to use a nail bar to pry the facia away from the slide .once removed we can install new fascia with screws and new finish nails to secure to slide out .fascia length is 152 1/2 inches

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #02: **0.00**

Job #03 - Warranty
DAMAGE TO CABINET BEHIND TV

Labor

Job #	Description	Total
03	Damaged fascia (WARRANTY)	N/C

Subtotal for Job #03: **0.00**

Job #04 - Warranty
COMPLAINT: TRIM BEHIND TV/PANTRY DOOR BOWED

CAUSE: Baton trim behind tv is loose

CORRECTION: Need to add a few staples to trim stick to help,secure it to the wall paneling better ,requesting 10 mins for repair

Labor

Job #	Description	Total
04	TRIM MOLDING REMOUNT TO WALL	N/C

Subtotal for Job #04: **0.00**

Customer Work Order

Job #05 - Warranty
COMPLAINT: STYLE DAMAGED WHERE PANTRY DOOR SHUTS

CAUSE: Style is damaged where pantry door shuts

CORRECTION: Style is damaged due to the door over closing and rubbing against the style during transport ,need to order and replace style and add rubber stops to prevent further damage to new style .In order to remove the right side style of the shelves I will need to remove all four shelves and the top and the bottom style to gain better access to remove the actual damaged piece of style.will need to remove all 4 shelves on the right side of the pantry. Removing the shelves will require me to remove the framing support for each shelf by removing the seven screws underneath of each shelf and then removing the staplesFor the style on the front of each side for shelves. Requesting 30 minutes per shelf. There is four shelves Once the shelves are removed I can then start to remove the side trim that is damaged that needs to be replaced.Will need to remove the multiple screws that are screwed city one by one support on the back of the style and that should remove it from the wall. Requesting 45 minutes to remove the right side damaged style . once all of the shelves in the top bottom and sides style or remove I can then cut a new style cut a new style to size and then install the reinstall the shelves individually one at a time once all of the shelves and the top and the bottom style are reinstalled I can then reinstall the right side damaged facia with a new piece and then staple up and secure in the place accordingly. Requesting 4 1/2 hours for removal Replacement and installation of new style. Style dimensions are 3in x 74 in

Labor

Job #	Description	Total
05	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #05: **0.00**

Job #06 - Warranty
COMPLAINT: PANTRY DOOR RUBS AT TOP
NO PARTS NEEDED

© 2026 Integrated Dealer Systems

CAUSE: Pantry door frame is loose and the door rubs at the top

CORRECTION: Need to remove plastic door frame and add shims accordingly to adjust the gap of the pantry door when shut . Will require me to peel away plastic piece glued to wood door frame and then scrape away all old adhesive. Then I can add shims as needed to help adjust the door frame gap and allow proper space for the door to close at the top. Once shims are added we can then re install the plastic door frame and test .requesting 1 hr for repair and install of shims

Labor

Job #	Description	Total
06	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #06: 0.00

Job #08 - External
COMPLAINT: WARRANTY ITEM

CAUSE: Baton trim is peeling

CORRECTION: Need to order new 1 1/2 in by 170 in baton trim to replace peeling pieces requesting 20 mins for removal and installation of new trim

Labor

Job #	Description	Total
08	Baton trim above dinette is peeling	0.00

Subtotal for Job #08: 0.00

Customer Work Order

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**0.00**

NOTICE:
DUE TO A LACK OF SPACE, A $15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 03 Sep 2026

Customer Signature : _____

© 2026 Integrated Dealer Systems