BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78037
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11670 - 2026 SPRINGDALE 2300BH 4YDTSGK26T7101230
VIN: 4YDTSGK26T7101230 HIN: SER#: 4YDTSGK26T7101230
Mileage: 0 Work Order Comp: 30 OCT 25
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 14 OCT 25 Inv #: 423954

| WO # | Job # | Description | JOB INFORMATION |
|---|---|---|---|
| 78037 | 2 | LP TANK HOLDER BASE IS MOUNTED TO FAR BACK AND INTERFERRING WITH THE BATTERY INSTALL AND WEIGHT DISTRIBUTION BRACKETS | Lp tank base was interfering with hitch brakets<br>Took lp tanks off and took lp tank base off and moved forward to give room for hitch brakets. And i moved breakaway switch because lp base had it covered up. |
| 78037 | 3 | ENTRY DOOR NEEDS ADJUSTED | Entry door needs adjusted<br>Had to adjust the latch to the screen door because it wouldn't release from main door. Then the main door was bowed that i got it adjusted so the door shuts properly now |
| 78037 | 4 | THE WATER HEATER DOOR WILL NOT CLOSE ALL THE WAY BECAUSE IT COMES IN CONTACT WITH THE SIDING WHEN TRYING TO CLOSE. | Water heater door not latching<br>So inspection of the water heater door found that the door latch was not close to latching. So i seen the screws were shot in at a angle. So i took the door frame off and seen that the hole was cut in the camper way bigger than the water heater. So i add a 1/2 in shim on the top and both sides i added a 1/4 in shim and put a new door frame on and the door latches properly. So i put new budle tape on the back of the door frame and shot the new screws in straight and the door works properly. So then i sealed the outside of the door frame with clear silicone. And then i sealed up the inside of the door frame and the water heater with |

Claim : 78037

| WO # | Job # | Description | JOB INFORMATION |
|---|---|---|---|
| | | | black silicone just like the factory did. Good to go now. Door look straight now. |
| 78037 | 5 | THE INLET PORT FOR THE SHORE POWER TWIST LOCK WAS INSTALLED UPSIDE DOWN. | Shore cord power outlet twisted<br>After inspection of the shore cord outlet seen that when the cord was lock into position it was sideways instead of it cord hanging straight down. So i took plug off camper and spun the center of the plug in the housing so the cord would be hanging correctly and then i secured it and remountec it to the camper. |
| 78037 | 6 | THE REFRIGERATOR DOOR KEEPER IS NOT ALIGNED PROPERLY AND THE REFRIGERATOR DOORS HIT IT WHEN TRYING TO CLOSE | Refrigerator door keeper is hitting the door<br>After inspection of the refrigerator i noticed that the door was not shutting all the way. It was the door keeper that was hitting the top of the door. So i adjusted the door keeper so it didn't hit the refrigerator door but then it hit the freezer door so i put a nylon washer under the freezer door to shim it up. Now both freezer door and refrigerator door closes properly and the door keeper works properly. Good to go |

| Lab Code | Job# | Description | LABOUR | Hrs | Rate | Total |
|---|---|---|---|---|---|---|
| Z990 | 2 | MISCELLANEOUS | REPAIR | 0.00 | 180.00 | 0.00 |
| Z990 | 2 | MISCELLANEOUS | REPAIR | 0.20 | 180.00 | 36.00 |
| Z990 | 3 | MISCELLANEOUS | REPAIR | 0.20 | 180.00 | 36.00 |
| Z990 | 4 | MISCELLANEOUS | REPAIR | 0.00 | 180.00 | 0.00 |
| Z990 | 4 | MISCELLANEOUS | REPAIR | 1.00 | 180.00 | 180.00 |
| Z990 | 5 | MISCELLANEOUS | REPAIR | 0.20 | 180.00 | 36.00 |
| Z990 | 6 | MISCELLANEOUS | REPAIR | 0.20 | 180.00 | 36.00 |

| | |
|---|---|
| Parts Total: | 0.00 |
| Labour Total: | 324.00 |
| Sublet Total: | 0.00 |
| Extras Total: | 0.00 |
| >>>>> Claim Total: | 324.00 |

Customer Signature:_____ Date: _____