



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26536



WO #: 26536

Customer: 93399 - WEBB, JOHN
Address:

Home Phone: 276-275-4536

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
Stock Desc: 2025 TT FOREST RIVER EAST TO
WEST
Model:
Serial #: 5ZT2DERB2S9015465
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 08 DEC 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: SHOWER FLOOR FLEXES ALOT CHECK AND ADVISE A BETTER SUPPORT

CAUSE: NOT SHOWING A BRACE UNDERNEATH THE SHOWER PAN ALLOWING IT TO GIVE IN THE MIDDLE

CORRECTION:

REMOVE AND REINSTALL SHOWER PAN, ALL WATER LINES AND PLUMBING, ADD I-BEAMS FOR SUPPORT, RESEAL ALL AREAS
LABOR 3.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: TPO ROOF IS SHOWING OSB GRAIN CHECK AND ADVISE

CAUSE: ROOF MEMBRANE IS DEFECTIVE BECAUSE THE WOOD GRAIN SUBSTRATE IS TELEGRAPHING THROUGH. PREMATURE ROOF FAILURE THAT WILL ALLOW CRACKING AND WATER INTRUSION.

CORRECTION: REMOVE AND REINSTALL ALL ROOF COMPONENTS (A/C, VENTS ETC.) PULL CURRENT ROOF MEMBRANE, PUT OVERLAY ON ROOF AND THEN INSTALL NEW ROOF MEMBRANE
LABOR 35.0

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93399
WEBB, JOHN



Customer Signature : _____

Date: 18 Dec 2025

W/O: 26536

Customer Work Order



Customer #: 93399
WEBB, JOHN

