



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25652 BOURGEOIS, KIRK



Estimate: 25652 (Appointment Date: 23 JUN 2025 - Time: 09:00am)

Customer: 92180 - BOURGEOIS, KIRK
Address: 217 RACCOON VALLEY RD
NEWPORT, TN
37821

Home Phone: (423) 237-8828

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #: 419022

Stock #:
Stock Desc: 2016 A FLEETWOOD BOUNDER
Model:
Serial #: 123456
Chassis #:
Mileage: 29792
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 23 JUN 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 23 JUN 25
Warr. Date:

Job #1 - External

COMPLAINT: WASH UNIT

CORRECTION: UNIT WASHED

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
WASH	WASH COACH	0	200.00	0.00

Subtotal for Job #1: 0.00

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

CORRECTION: ROOF LOOKS GOOD AT THIS TIME, NEWER ROOF TECH STATED

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

COMPLAINT: CS THAT THE FRIDGE IS FREEZING UP AROUND THE VENTS CHECK AND ADVISE

CORRECTION: FRIDGE NEEDED TO BE DEFROSTED. TECH WENT OVER THE FRIDGE WITH BOTH CUSTOMERS FRIDGE PULLED CORRECT TEMPS AFTER DEFROSTED

Labor

Code	Description	Hours	Rate	Total
Z990	DEFROSTED FRIDGE	0	175.00	0.00

Subtotal for Job #3: 0.00

Job #4 - External

CUSTOMER IS WAITING UNIT IS LIVED IN



Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: SLIDE TOPPER AWNING CHECK AND ADVISE

CORRECTION: SLIDE TOPPER AND AWNING FABRIC ARE BOTH STRETCHED OUT AND WILL NEED TO BE REPLACED

Labor

Code	Description	Hours	Rate	Total
Z990	CHECKED AND ADVISED LINE 5,6 AND 7	0	175.00	0.00

Subtotal for Job #5: 0.00

Job #6 - External

COMPLAINT: BIG SLIDE ON DRIVER SIDE IS DRAGGING THE LINO FLOOR AND SLIDE IS MAKING NOISE WHEN IT IS COMING IN

CORRECTION: THIS SLIDE DOES NEED TO BE ADJUSTED TO NOT DAMAGE THE LINO FLOORING TECH STATED THE SLIDE IS SEALING GREAT ADJUSTMENT WILL BE CUST CALL

Subtotal for Job #6: 0.00

Job #7 - External

COMPLAINT: WHEN ENTRY DOOR OPENS THE LIGHTS GO DIM IN THE COACH

CORRECTION: LIGHT SWITCH IS A DIMMER SWITCH PRESS AND TO DIM AND BRIGHTEN THIS IS THE DESIGN

Subtotal for Job #7: 0.00

Job #8 - External

COMPLAINT: THE AWNING OVER THE ENTRY DOOR ALLOWS WATER TO DRAIN DOWN BEHIND IT AND THE AWNING IS LOWER ON ONE END MORE THAN IT SHOULD

CORRECTION: AWNING IS BENT DOWN AND WILL NEED TO BE REPLACED

Subtotal for Job #8: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	0.00
Estimate Total:	0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 24 Jun 2025

