

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2532219
<b>12024 CENTRAL AVE S.E.</b>		<b>CLAIM ORIGIN</b>	WEB
<b>ALBUQUERQUE, NM 87123</b>		<b>ORIGINAL CLAIM ID</b>	
<b>USA</b>		<b>VIN</b>	5ZT3SN3B0SG705875
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	049 / 049A
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	SNF3802FLWB
<b>DOMINIC MALDONADO</b>		<b>DEALER RO #</b>	72649
<b>6312 CANAVIO PL N/W</b>		<b>CLAIM START DATE</b>	12/18/2025
<b>Albuquerque, NM 87120</b>		<b>CLAIM END DATE</b>	04/17/2026
<b>USA</b>			
<b>Retail Date of Purchase</b>	10/23/2025	<b>WARRANTY EXPIRATION DATE</b>	10/23/2026

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	30-101-24-00-001079	<b>Operational Description</b>	Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code
<b>Complaint, Cause, Correction</b>	Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:11:26 :: Complaint: Customer states sliding door to bedroom is loose at the track Cause: Pocket door fell off the track Correction: Removed the upper trim to reinstall door into track and reinstall upper trim		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$57.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$57.00
<b>Notes</b>			

### Labor

**Line# 2**

<b>Operation Code</b>	30-102-12-00-001096	<b>Operational Description</b>	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code
<b>Complaint, Cause, Correction</b>	Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:13:09 :: Complaint: Customer states ceiling trim at kitchen is loose Cause: Trim above the kitchen is popped out Correction: Tapped trim back into place		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b> \$19.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b> \$19.00
<b>Notes</b>			

### Labor

**Line# 3**

<b>Operation Code</b>	20-46-01-00-000726	<b>Operational Description</b>	Window Screen - Exterior/Windows/Replace/No Tread Code
<b>Complaint, Cause, Correction</b>	Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:19:43 :: Complaint: Customer states screen on the window at the dinette has a tear Cause: Window screen is damaged Correction: Replace window screen		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b> \$19.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b> \$19.00
<b>Notes</b>			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	USERPART	31-1608 Screen - Black			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	<b>Sub Qty</b>	<b>Sub Dlr Price</b>	<b>Sub Freight</b>	<b>\$0.00</b>	
	<b>Appr Qty</b>	<b>Appr Dlr Price</b>	<b>Appr Freight</b>	<b>\$0.00</b>	

Notes

Labor

Line# 4      **Operation Code**                      **Operational Description**  
 60-138-01-00-001525                      Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:21:09 :: Complaint: Both the fresh and black tanks are missing the handles Cause: Found 3 dump handles missing Correction: Replace 3 dump handles

Model#	Dlr Sub Hrs	0.15	Sub Labor Amt	\$28.50
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

This is for part only no labor per dealer's description. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1      **Item #**                                      **Description**  
 USERPART                                      11-0086 Waste valve extension kit

Model #	Serial #	Part tag
Sub Qty      2.00	Sub Dlr Price      \$24.13	Sub Freight      \$0.00
Appr Qty      2.00	Appr Dlr Price      \$24.13	Appr Freight      \$0.00

Notes

Line# 2      **Item #**                                      **Description**  
 60P14615A                                      HANDLE, T1003-6N, BLACK, 19462 HANDLE, T1003-6N, BLACK, 19462

Model #	Serial #	Part tag
Sub Qty      2.00	Sub Dlr Price      \$4.81	Sub Freight      \$16.26
Appr Qty      2.00	Appr Dlr Price      \$1.36	Appr Freight      \$16.26

Notes

Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5420089. The approved cost has been adjusted to \$0.59 + state allowed mark-up of 15%.

Line# 3      **Item #**                                      **Description**  
 60P15611A                                      T-HANDLES FOR WASTEGATE VALVE GRAY, T1003-6GN-0, 34054

Model #	Serial #	Part tag
Sub Qty      1.00	Sub Dlr Price      \$0.83	Sub Freight      \$0.00
Appr Qty      1.00	Appr Dlr Price      \$0.84	Appr Freight      \$0.00

Notes

Computer rounded up \$0.01

Labor

Line# 5      **Operation Code**                      **Operational Description**  
 20-69-02-00-000705                      Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:23:51 :: Complaint: Customer states drivers side front compartment door is misaligned and the brackets for the gas struts are loose and not straight Cause: Door is out of alignment and the strut brackets are loose Correction: Realigned compartment door and tighten down the strut brackets

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

The time for this repair has been adjusted. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

Labor

Line# 6      **Operation Code**                      **Operational Description**  
 70-147-24-00-001660                      Electric TV Lift Mechanism - Appliances/Television/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:25:49 :: Complaint: Customer states the TV lift makes noise and binds while operating Cause: TV light mechanism is noisy when being used, checked all lift hardware for any loose screws Correction: Lubricated all moving parts

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
--------	-------------	------	---------------	---------

Serial# Appr Hrs 0.10 Appr Labor Amt \$19.00

**Notes**

The time for this repair has been adjusted. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

**Labor**

Line# 7

**Operation Code** 40-196-01-11-001277 **Operational Description** Ceiling Décor Light - Electrical/12 Volt Interior/Replace/Electrical

**Complaint, Cause, Correction**

Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:27:37 :: Complaint: Customer states lights are misaligned in the kitchen Cause: Kitchen lights are out of alignment Correction: Bent kitchen lights back into place Additional Note : stephanie@dealer-advisors.com, 2025-12-18 18:29:53 :: \*\*This is not a replacement of the light, just a repair to the fixture to straighten it out\*\*

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$38.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

**Notes**

**Labor**

Line# 8

**Operation Code** 40-196-01-11-001278 **Operational Description** Ceiling Décor Light Globe(s) - Electrical/12 Volt Interior/Replace/Electrical

**Complaint, Cause, Correction**

Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:30:41 :: Complaint: Customer states lights over the dinette do not match Cause: Dinette lights are not the same Correction: Replace light

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00

Serial# Appr Hrs 0.50 Appr Labor Amt \$95.00

**Notes**

\*\*\*Checking with parts to see if they can just get the globe.

Ok. Thank you!

\*\*\*The globes are NLA you will have to go with what is current.

**Part**

Line# 1

**Item #** F100323480 **Description** LIGHT, PENDANT, TEXTURED BLACK, w/ BLACK LANTERN MESH SHADE, REPLACEMENT FOR (F100122299) SEND 2 , GSD5464

**Model #** **Serial #** **Part tag**  
Sub Qty 2.00 Sub Dlr Price \$156.43 Sub Freight \$20.50  
Appr Qty 2.00 Appr Dlr Price \$156.43 Appr Freight \$20.50

**Notes**

**Labor**

Line# 9

**Operation Code** 30-100-01-00-001054 **Operational Description** Kitchen/Galley Countertop - Interior/Cabinetry/Replace/No Tread Code

**Complaint, Cause, Correction**

Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:34:40 :: Complaint: Bar countertop is cracked Cause: Countertop has a crack along the edge Correction: Remove and replace countertop

Model# Dlr Sub Hrs 0.40 Sub Labor Amt \$76.00

Serial# Appr Hrs 3.50 Appr Labor Amt \$665.00

**Notes**

I authorize the time that the dealer is requesting for replacement this is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met. So the dealership can add more information for more time.

.25hrs to remove and reinstall sofa  
3.50 hrs to remove and reinstall wall panel / have to remove all batten strips / remove all staples / remove silicone and clean / remove two 110v receptacles. / reinstall panel and all trim / fill all staple holes

.75hrs to remove and replace countertop / pre-drill holes / reseal  
Additional photos added as well  
I have adjusted the time the dealer has requested to replace; replacement is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

**Part**

<b>Line# 1</b>	<b>Item #</b>		<b>Description</b>			
	F100438517		TOP, BUFFET, OHC, CHILI REDWOOD, 70.25" X 13.25", (49-WDC189), PRINT# 12-002474, 7202154			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	1.00	Sub Dlr Price	\$83.28	Sub Freight	\$56.43
	Appr Qty	1.00	Appr Dlr Price	\$83.28	Appr Freight	\$56.43

**Notes****Labor**

<b>Line# 10</b>	<b>Operation Code</b>		<b>Operational Description</b>		
	30-101-01-00-001088		Closet Wardrobe Door - Interior/Interior Doors/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>				
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 18:36:57 :: Complaint: Customer states closet doors for bedroom have damaged wood at the latches Cause: Closet doors are damaged Correction: Remove and replace closet doors				
	<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$190.00
	<b>Serial#</b>	<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b>	\$190.00

**Notes**

I authorize the time that the dealer is requesting for replacement this is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

**Part**

<b>Line# 1</b>	<b>Item #</b>		<b>Description</b>			
	30I04029A		MIRROR, 5/32" 19 1/2" x 63 1/2" - CC SAFETY BACK   USED IN SPARTAN 37628			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	4.00	Sub Dlr Price	\$168.18	Sub Freight	\$0.00
	Appr Qty	4.00	Appr Dlr Price	\$168.18	Appr Freight	\$0.00

**Notes**

<b>Line# 2</b>	<b>Item #</b>		<b>Description</b>			
	F100440282		DOOR, CABINET, 25" X 69", CURIO W/3-1/2" RAIL, CHILI REDWOOD, 656135			
	<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
	Sub Qty	2.00	Sub Dlr Price	\$359.80	Sub Freight	\$341.47
	Appr Qty	2.00	Appr Dlr Price	\$359.80	Appr Freight	\$341.47

**Notes**

<b>Submitted</b>	Labor Amt	\$617.50	<b>Approved</b>	Labor Amt	\$1,140.00
	Parts & Freight	\$1,235.33		Parts & Freight	\$1,231.89
	Total	\$1,852.83		Total	\$2,371.89

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

All repairs described have been inspected and are satisfactory.