

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79286
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 10558 - RICHARD L. WAHL, JR.
Address: 220 HERNDON DR.
EVANSVILLE,
47711
Phone: 812-431-2114
Stock Number: 11651 - 2026 DELTA 281BH 7M5TD3126TC307285
VIN: 7M5TD3126TC307285 HIN: SER#: 7M5TD3126TC307285
Mileage: 0 Work Order Comp: 10 APR 26
Auth. No: Dealer #:
Warr. Date: 28 FEB 26 Work Order Date: 18 MAR 26 Inv #: 428546

WO # Job # Description JOB INFORMATION

79286 1 SCRATCH ON TRIM IN SLIDE ROOM ABOVE RECLYNER ON TOP LEFT SIDE
WHEN STANDING IN FRONT OF RECLYNER
Retrieved unit and hooked up Shore power. Compartment was locked
with disconnect... pulled door cylinder and retrieved Key for
Compartment and turned disconnect ON. Took pics and submitted
part request for Facia Board with chips in it. Turned disconnect
back off, disconnect Shore power and put back into storage.

79286 6 TABLE HAS CHIP IN THE CORNER.
Took pics and measurements, 29in x 32in x 1in and submitted part
request.

79286 3 WHEN CUSTOMER RAN THE SLIDE ROOM OUT IT TORE A SPOT IN THE FLOOR
Found and took pics of cut on vynle floor.

79286 4 MAGNET AND SCREW HAS COME OFF OF THE BOTTOM DRAWER
Remount Magnet for internal drawer.
Located the drawer customer was talking about after hunting thru
the unit... turned out the drawer was Located inside and behind
Cabinet Doors under TV. Remounted Magnetic catch.

79286 5 SCREEN IN DOOR BY BUNK HAS HOLE IN THE SCREEN
Damaged screen
Took pics, measured and cut new piece of screen. Removed old
screening from damaged section of door. One single insert that
holds the screening in is installed on whole door including top

Claim : 79286

 WO # Job # Description JOB INFORMATION

and bottom section... i had to center the new screening and work from the top middle down each side which was difficult to keep screen tight while keeping slack out of insert while also forcing insert into track but i managed and cut extra off.

79286 8 BLIND BEHIND RIGHT SIDE OF COUCH IS CROOKED
 Blind mount brackets were pulled from their mounted positions The lock mounted brackets that secures blinds in place was onky being held up by the center mount... both of the end mounts were pulled from the blind covers where they mount. Had to drop the blind and unclip the brackets off of blind and reinstall them and reinstall blind.

 Part No Job# Description PARTS Qty Price Total

 33854 1 Fascia - 5.50 x 144 - Salinas Oak 1.00 17.10 17.10
 ALL34990 6 TOP - Dinette - 29 x 32 w/Grooves 1.00 150.66 150.66

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.41 195.00 79.95
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.06 195.00 11.70
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.13 195.00 25.35
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.80 195.00 156.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50

 Job# Sublet Description SUBLET Total

 3 LINO REPAIR 425.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-FASCIA 1.00 203.91 203.91
 FRT 6 UPS-TABLE TOP 1.00 29.47 29.47

Parts Total: 167.76
 Labour Total: 370.50
 Sublet Total: 425.00
 Extras Total: 233.38

>>>> Claim Total: 1,196.64

Customer Signature: _____

Date: _____