



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH836 38 {PA03975505 }	Reference no.	79152	Status	Approved
--------------------------	--------------------------------------	---------------	-------	--------	----------

Serviceing Dealer	1194	Name	Basden's American RV	Address	600 E Baseline Rd Evansville, IN 47725	VIN	4YDFCGR2XT2505130	Retail sold on	
-------------------	------	------	----------------------	---------	---	-----	-------------------	----------------	--

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root				Approved	Actual		Base	
Operation Description	Sublet	Sub Hours	Hours	hours	hours	Qty	hours	Complaint/Cause/Correction
6201106B	Regulator - Replace	0	0.5	0.5		1	0.3	Complaint: REGULATOR MAXES OUT AT 10 Cause: Lp regulator Correction: During the pdi was running the lp drop test and the lp regulator wouldn't go above 10 wc. Lp regulator didn't make a sound. Got a new lp regulator. Shut off the lp the disconnect the lp tank on the off doorside. Disconnected the lp lines from the lp regulator. Put pipe thread sealer on the lp hoses and connected to the new lp regulator. Tested the new lp regulator and it made noise of flow. The manometer was reading correctly. KRV- Approved to Repair
3201806A	Decorative Wood Trim - Repair - per piece	0	1	0.1		1	0.1	Complaint: SCRATCH ON TV LID Cause: Scratch Correction: Took pictures and put in a parts request for a new tv cover KRV- Approved to repair not replace
3201812B	Decorative Wood Trim - Replace - per piece	0	0.2	0.2		1	0.2	Complaint: BATHROOM FLOOR TRIM HAS STRECH MARKS Cause: Damaged trim Correction: Took pictures and put in parts request for new trim
2104402A	Slide Out - Box - Fascia - Interior Trim - Repair	0	0.2	0.1		1	0.1	Complaint: BIG SLIDEROOM FACIA TRIM IS WARPED Cause: fascia trim Correction: Stapled the trim then covered with filler.
2200203A	Corner Moldings - ODS - Ft - Repair	0	0.2	0.2		1	0.2	Complaint: OFF DOOR SIDE CAP IS MISSING SEALANT Cause: No silicone Correction: Took pictures of the cap corner trim with no silicone and applied silicone to fill the void.
2100208B	Bulkhead Cover	0	5	4		1	4	Complaint: DENT ON LOWER METAL Cause: Dent Correction: Took pictures of the dent then put in a parts request for new sheet of metal or fiberglass.

For paper claims only use one pre-authorization number per warranty claim form.
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.