

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
MYERS RV CENTER INC
12024 CENTRAL AVE S.E.
ALBUQUERQUE, NM 87123
USA

CLAIM STATUS Authorized
CLAIM 2593660
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2AVSB2TB941670
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 050 / 050
ITEM # AVT27REI
DEALER RO # 72965
CLAIM START DATE 02/27/2026
CLAIM END DATE 01/01/1900

Labor rate: \$190.00
OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-27 09:10:11 :: Complaint: Multiple decals torn on driver and passenger side Cause: Decals are torn and bubbled Correction: Replace avenger decal, driver side upper black decal, upper passenger side black decal

Model#	Dlr Sub Hrs	2.25	Sub Labor Amt	\$427.50
Serial#	Appr Hrs	2.25	Appr Labor Amt	\$427.50

Notes

Can you please see if some of the decals can be saved by doing relief cut and use heat gun and squeegee. I knpw some need replaced. and see what your time would be. TD
The concern that the tech has is that some of the bubbles are long and big and pricking them may cause them to rip
All you can do is the best you can and we will go from there. TD
The entire Avenger decal is going to need to be replaced, and then there are 5 areas that needs to have the bubble popped and smooth out. Requesting 1.0 hour for the decal replacement, and .25 hours for each bubble repair.
NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. TD

Submitted	Labor Amt	\$427.50
	Parts & Freight	\$0.00
	Total	\$427.50

Approved	Labor Amt	\$427.50
	Parts & Freight	\$0.00
	Total	\$427.50

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.