



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH932 Reference no.79340 71 (PA03984791)	Status	Approved		
Servicing Dealer	1194	Name	Basden's American RV	Address	600 E Baseline Rd Evansville, IN 47725
				VIN	4YDTCGM29TV505757
				Retail sold on	

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root		Approved			Actual	Qty	Base	Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours		hours	
3102803B	Dinette Table - Replace	0	0.3	0.2		1	0.2	Complaint: KITCHEN TABLE HAS A SCRATCH ON IT Cause: Table scratched Correction: Remove and replace table KRV — Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
5104402A	Switch, 12V - Repair	0	0.2	0.2		1	0.2	Complaint: the sensor for the panty light is not working Cause: Sensor needed adjustment Correction: Moved sensor slightly. Seems to be working now KRV — REPAIR ONLY approved.
3201802A	Decorative Wood Trim - Repair - per piece	0	0.1	0.1		1	0.1	Complaint: TRIM NEXT TO THE TV IS POPPING OUT Cause: Trim unglued Correction: Glued trim back into place KRV — REPAIR ONLY approved.
4201808B	Awning - Main - Hardware - Replace - Complete	0	1.5	1		1	1	Complaint: THE AWNING ARM IS A LITTLE BENT Cause: AWNING ARM IS BENT Correction: REPLACE WITH NEW KRV — Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
3201806A	Decorative Wood Trim - Repair - per piece	0	0.1	0.1		1	0.1	Complaint: BATHROOM DOOR TRIM IS POPPING OFF Cause: Trim pulled off Correction: Popped trim back into place KRV — REPAIR ONLY approved.
5102503B	Light, 12V Interior - Lens/ Globe	0	0.2	0.1		1	0.1	Complaint: THE COVER FOR THE SHOWER LIGHT IS MISSING Cause: Cover missing Correction: Install new cover KRV — Labor time approved and adjusted in accordance with Keystone RV's flat rate manual
4205602B	Range Hood - Replace - Complete	0	0.5	0.3		1	0.3	Complaint: THE VENT FOR THE RANGE HOOD HAS A SCRATCH Cause: Factory defect Correction: Remove and replace vent

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.