



Claim CLAIM91705 (C3935015)

Last Modified By

										Changed		
Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	warranty rate	Date of Type	Purchase	
CLAIM91705 (C3935015)	40278	4/1/2026	4/1/2026	4YDTATL27T8920350	PA03980623	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970	

Deny code	Item number	Name	Quantity	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
90	578844	Light - Tail - Black Base - w/License Bracket - LED - RVSTLB0061	1	0	8.38	30.00	10.89	25.17	25.17	0.00	Approved

inv 5149009 Component Serial Number 815 8/21/25

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5101906B	Light, Clearance & Taillight - Replace	0.2	0.2	33	0	1	0.2	Approved
Complaint Dealer states the DS back taillight is cracked and will not stay attached. Cause Taillight cover is cracked around the mounting tab causing the cover to keep falling off when the trailer is moving. Correction Will need a new tail light with license plate holder and rewire light when part is received. KRV – Labor time approved and adjusted in accordance with Keystone RV’s flat rate manual.									

Submitted parts & subLet	10.89	Approved parts & subLet	10.89
Submitted labor & subLet	33.00	Approved labor & subLet	33.00
Submitted freight	25.17	Approved freight	25.17
Total Submitted	69.06	Total approved	69.06