



Claim CLAIM91709 (C3935020)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Changed		Date of Purchase
								Labor rate	warranty rate	
CLAIM91709 (C3935020)	40280	3/25/2026	3/25/2026	4YDTATL22T8920353	PA03980628	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR 1/1/1970

Deny code	Item number	Name	Qty	Dealer price	Part Markup	Appr Freight	Sub Freight	Sublet	Status		
93	578844	Light - Tail - Black Base - w/License Bracket - LED - RVSTLB0061	1	0	8.38	30.00	10.89	25.17	25.17	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5101906B	Light, Clearance & Taillight - Replace	0.2	0.2	33	0	1	0.2	Approved

Complaint Dealer states taillight is cracked.

Cause Taillight cover is cracked around the mounting tab causing the cover to keep falling off when the trailer is moving.

Correction Will need to R&R taillight with license plate holder and re-wire the taillight. Verify it works.

KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

KRV - Please retain part for possible return or additional photos. Keystone will notify you within 48 hours of submitting your claim for disposition of the part. Model+serial #s / vendor tags from complete component / vendor markings required.

Submitted parts & subLet	10.89	Approved parts & subLet	10.89
Submitted labor & subLet	33.00	Approved labor & subLet	33.00
Submitted freight	25.17	Approved freight	25.17
Total Submitted	69.06	Total approved	69.06