

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13143B

Date In: 07 MAY 26 Author: KOTT  
Promised Date: 25 DEC 26 Stock No: 11379  
: Year: 2025  
Customer Name: 9852 - BRONIEC, GREGOR Manufacturer: GRAND DESIGN  
Address: 1142 W QUEENS WAY Brand: REFLECTION 100 SERIES  
: NEKOOSA, WI Model: 22RK  
Postal/Zip: 54457 Miles/Hrs:  
Phone#(res): 715-459-1101 Exterior Color:  
Phone#(bus): Unit Type: FW-FIFTH WHEEL  
Cell Phone: License#:  
Email: gbronic@wctc.net Tag#: DB: 5/7  
Purchased Date: 03 APR 25 :  
Delivery Date: 30 MAY 25 :  
InService Date: :  
Serial#: 573FR2820S3353351 :

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
WARR COMPLAINT: WARRANTY REPAIR 1 - RUST ON THE ENTRY W 1020 GRAND
      STEPS, WELDS ON TOP STEPS.
      CAUSE: look at entrance steps for rust. WOULD
      NEED TO PAINT THE STEPS OR REPLACE THE
      STEPS- IT WILL BE DEPENDENT ON HOW
      MANUFACTURER WOULD LIKE TO PROCEED.
      CORRECTION: .... REQ: .40 TO PAINT THE STEPS REQ:
      1 HOUR IF MANU WANTS US TO REPLACE THE
      STEPS
WARR COMPLAINT: WARRANTY REPAIR 2 - RECLINER, RIGHT SIDE W 1020 GRAND
      WHILE FACING, IS CROOKED AND FOOT
      SUPPORT CATCHES WHEN LOWERING.
      CAUSE: check right hand recliner for operation.
      catches on the frame when closing. the
      scissor part is tweaked. need to order
      new right hand recliner.
      CORRECTION: ... REQ: 1.5 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 3 - WATER LEAKS FROM W 1020 GRAND
      UNDER SHOWER UNIT OR AROUND SHOWER DOOR
      FRAME. CMR STATES I AM NOT SURE WHERE IS
      IS COMING FROM, BUT IT APPEARS TO COME
      FROM UNDER THE UNIT.
      CAUSE: check shower door track for sealant.
      needs to be recaulked.
      CORRECTION: ... REQ: .50 HOURS OF LABR
WARR COMPLAINT: WARRANTY REPAIR 4 - RENOGY INVERTER DOES W 1020 GRAND
      NOT WORK, NO AC CURRENT IN THE CAMPER
      EVEN WHEN CAMPER IS PLUGGED IN.
```

Continued on page 2

Work Order : 13143B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   check inverter for operation. will not
         power up. check voltage at inverter.
         it's got 13.4 dc volts going in. but
         will not power up. will need a new
         inverter.
CORRECTION: .... REQ: 1.50 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.00  140.00  0.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.50  140.00  70.00
ARR02 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.00  140.00  0.00
ARR02 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.15  140.00  21.00
ARR03 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.00  140.00  0.00
ARR03 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.06  140.00  8.40
ARR04 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.00  140.00  0.00
ARR04 Z992    MISC LABOUR CODE (WARR TD  W-1020  0.35  140.00  49.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1020      0.00  148.40  0.00  0.00  0.00  148.40
Totals      0.00  148.40  0.00  0.00  0.00  148.40

```

&k2S  
&k0S