

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2532135 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 4X4TRPU16SB033424 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 080 / 080 <b>ITEM #</b> RPT192-80 <b>DEALER RO #</b> 72205 <b>CLAIM START DATE</b> 12/18/2025 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$190.00 <b>OWNER INFORMATION</b> STACY GARCIA 4618 SOLECITO LOOP Santa Fe, NM 87507 USA	
<b>Retail Date of Purchase</b> 06/14/2025	<b>WARRANTY EXPIRATION DATE</b> 06/14/2026

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	60-138-01-00-001537	<b>Operational Description</b>	
		Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code	

**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 16:58:14 :: Complaint: Customer states black valve is not fully shutting, waste seeps out past the valve. Cause: Found that the valve is defective Correction: Remove and replace valve

<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b> \$190.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$57.00

**Notes**  
 excessive time requested. Time reduced based on photos, description and flat rate.  
 authorized to replace valve as stated

### Labor

**Line# 2**

<b>Operation Code</b>	30-95-24-00-000958	<b>Operational Description</b>	
		Booth Structure - Interior/Dinette/Repair/No Tread Code	

**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:03:20 :: Complaint: Customer states booth end by entry door is loose and wood is delaminating Cause: Delamination Correction: Secure board to frame, but the top delaminating piece has to be ordered and replaced. Piece is 30"Lx2"Wx5/8" Additional Note : stephanie@dealer-advisors.com, 2025-12-18 17:09:24 :: \*\*chose labor code for the securing of the panel, the piece needing replacement is the top piece as shown in the picture\*\*

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b> \$95.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b> \$95.00

**Notes**  
 hello, an hour was already given to repair dinette booth on claim 2331393.  
 authorized to replace top stile

### Labor

**Line# 3**

<b>Operation Code</b>	30-99-01-00-001018	<b>Operational Description</b>	
		Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code	

**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:10:27 :: Complaint: Customer states the blind in the bathroom is frayed on the edge Cause: Fabric is frayed, component failure Correction: Replace shade, 30L x1 2 3/4W

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.25	<b>Sub Labor Amt</b> \$47.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$38.00

**Notes**  
 excessive time requested. Time reduced based on photos, description and flat rate.  
 authorized to replace blind

**Labor**

Line# 4

**Operation Code**

30-99-01-00-001018

**Operational Description**

Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code

**Complaint, Cause, Correction**

Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:12:27 :: Complaint: Daylight can be seen through the shade Cause: Defective fabric Correction:Replace shade, 31 1/4W x 24L

**Model#****Dlr Sub Hrs**

0.25

**Sub Labor Amt** \$47.50**Serial#****Appr Hrs**

0.20

**Appr Labor Amt** \$38.00**Notes**excessive time requested. Time reduced based on photos, description and flat rate.  
authorized to replace blind as stated**Labor**

Line# 5

**Operation Code**

20-66-02-17-000672

**Operational Description**

Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch

**Complaint, Cause, Correction**

Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:14:39 :: Complaint: Customer states the entry door is difficult to lock and pops open Cause: Lock is binding on the striker, screws on striker plate are making contact with the screen door and entry door Correction: Moved striker plate and adjust screws by tapping lightly on the screw head to allow enough clearance

**Model#****Dlr Sub Hrs**

0.20

**Sub Labor Amt** \$38.00**Serial#****Appr Hrs**

0.20

**Appr Labor Amt** \$38.00**Notes****Submitted**

Labor Amt

\$418.00

Parts &amp; Freight

\$0.00

Total

\$418.00

**Approved**

Labor Amt

\$266.00

Parts &amp; Freight

\$0.00

Total

\$266.00

**DEALER****DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER****DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.