

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2669189
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKEC1TY042695
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT16LP-95
		DEALER RO #	79843
		CLAIM START DATE	05/08/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-66-02-00-000678 Screen Door - Exterior/Entry Doors/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-08 10:27:30 :: SCREEN DOOR LATCH ON THE ENTRY DOOR NEEDS ADJUSTED Latch pushed down too far Adjusted latch up

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$39.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 60-136-01-00-001506 Combination City or Gravity Fill - Plumbing/Fresh Water Supply/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-08 10:29:03 :: THE WATER HOOK UP PANEL IS BENT REALLY BAD Bad factory install Remove and replace panel

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$58.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$58.50

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 20-66-02-00-000664 Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-08 10:30:50 :: ENTRY DOOR IS HARD TO CLOSE Striker plate adjusted too far inward Adjusted plate outward

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$58.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$58.50

Notes

Labor

Line# 4 **Operation Code** **Operational Description**
 30-100-36-00-001050 Cabinet Stiles - Interior/Cabinetry/Touch Up/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-08 10:31:23 :: STAPLE HOLES ABOVE THE DINNETT NEEDS TO BE FILLED Factory missed the staple holes Filled with wood putty

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$19.50
Serial#	Appr Hrs	0.10	Appr Labor Amt \$19.50

Notes

Labor

Line# 5

Operation Code

30-92-15-16-003391

Operational Description

Wall Stud - Interior/Interior Miscellaneous/Repair or Replace/Structure

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-05-08 10:32:01 :: NASTY WOOD SPLINTER BETWEEN UPPER CABINET AND INTERIOR WALL Poor craftsmanship Broken splinter off then pushed remaining up

Model#

Dlr Sub Hrs

0.20

Sub Labor Amt \$39.00

Serial#

Appr Hrs

0.20

Appr Labor Amt \$39.00

Notes

not seeing issue in photos

SORRY PHOTO ADDED

Submitted

Labor Amt

\$214.50

Parts & Freight

\$0.00

Total

\$214.50

Approved

Labor Amt

\$214.50

Parts & Freight

\$0.00

Total

\$214.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.