



Warranty Claim Form

Date: 5/18/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3128R3350305
Reflection 270BN
Retail Purchase Date: 4/29/2025
Work Started: 4/6/2026
Work Completed: 4/6/2026

Claim Status: Paid
Dealer Work Order #: 13204B
Unit Offline Date: 5/13/2024

Claim #: 985067
Labor: \$140.00
Parts: \$12.45
Shipping: \$4.41
Total: \$156.86

Notes: 420013 - please provide pictures of the light off of the unit, front and back. NN 5.5 AB 4/14 *Please hold all parts for a minimum of 30 days after the claim is paid* 310003 - This would not be something we would cover under warranty. This would be maintenance. 540012 - No issues found. This has been noted.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

SHARON ROKUS
1911 90TH STREET N
WISCONSIN RAPIDS, Wisconsin
54494
United States
7155709271

Operation Line # 1

Flat Rate Code: 110018 Underbelly - Reseal

Fault Code: Damaged/Maintenance

Problem: Underbelly has some openings that need to be sealed up.

Hours: .3

Cause: Underbelly needed to be resealed in multiple areas.

Amount: 42.00

Remedy: used expanding black foam to seal areas, pics taken before and after

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	2.10

Operation Line # 2

Flat Rate Code: 420013 Lights (Interior) - R&R LED Light

Fault Code: Component Failure

Problem: In the bathroom there is a motion light that is flickering. It does not just stay on as it should.

Hours: .2

Cause: There is good voltage going to the light, the sensor light is flickering and very dim.

Amount: 28.00

Remedy: Replace motion sensor light.

Sublet Repairs: \$0.00

Manufacturer #: .

Model #: .

Serial #: .

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
420689 LIGHT INTERIOR STEP LED BLACK MOTION WET LOCATION SURF MNT	LIGHT INTERIOR STEP LED BLACK MOTION WET LOCATION SURF MNT		1	1	6.85

Operation Line # 3

Flat Rate Code: 590017 Skirt Metal (Lower Wrap) - Resecure *Fault Code:* Improper Installation/Build

Problem: The DS dog leash holder pulled out and needs repair/replacement. *Hours:* .5

Cause: The manufacturer had two self tapping screws hold dog leash in place that came loose. *Amount:* 70.00

Remedy: We added 3 1/4" bolts with lock washer and secured bracket back into place. photos taken before and after. Unsure on proper labor code. *Sublet Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	3.50