



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64919
Promised Date: 14 AUG 21

CUSTOMER WORK ORDER

WO #: 64919

Customer: 50824 - MOORE, GARY -
812-449-1435

Tag:

Author: CAM

Location: 0816 CLOSE W/O

Stock #:

Stock Desc: 2021 5W KEYSTONE
MONTANA HIGH COUNTRY

Chassis #:

Serial #: 4YDF3312XMA741742

Mileage:

Licence:

Invoice #:

Date In: 04 AUG 21

Promised: 14 AUG 21

Date Sched:

Completed: 16 AUG 21

Warr. Date:

Job #1 - Warranty

COMPLAINT: SAFETY ADVISORY # 21-409

CAUSE: SAFETY ADVISORY # 21-409

CORRECTION: REMOVED UNDERBELLY AND INSPECTED 120VAC WIRING CONNECTORS. CONNECTORS WERE DAMAGED (1.0 HOUR ON EACH AFFECTED ROOM) NEEDED TO BE PROPERLY MOUNTED (.5 HOUR ON EACH AFFECTED ROOM). PROPERLY MOUNTED CONNECTORS AND REINSTALLED UNDERBELLY ON THE FOLLOWING SLIDE ROOMS: BOTH MAINFLOOR SLIDE ROOMS (2 TOTAL).

Labor

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR	JP	130.00

Subtotal for Job #1: 130.00

Parts Total: 0.00

Labour Total: 130.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 130.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Aug 2021



Customer #: 50824
MOORE, GARY



e-Authorization

27:16

e-Authorization number PA02906832 Reference no: 64919 Status: Approved VIN 4YDF3312XMA741742 1/2/2021 Approved by hold Retail sold on 8/20/2021

34 Basden's American RV Basden's American RV 600 E Baseline Rd Evansville, IN 47725

Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1 7140942A	Safety Advisory 2	0.00	1.00	1.00		1		Complaint:SAFETY ADVISORY # 21-409 Cause:SAFETY ADVISORY # 21-409 Correction:REMOVED UNDERBELLY AND INSPECTED 120VAC WIRING CONNECTORS. CONNECTORS WERE DAMAGED (1.0 HOUR ON EACH AFFECTED ROOM) NEEDED TO BE PROPERLY MOUNTED (.5 HOUR ON EACH AFFECTED ROOM). PROPERLY MOUNTED CONNECTORS AND REINSTALLED UNDERBELLY ON THE FOLLOWING SLIDE ROOMS: BOTH MAINFLOOR SLIDE ROOMS (2 TOTAL). KRV- 2 Slides

e-Authorization number PA02906832

1.00

r paper claims only use one pre-authorization number per warranty claim for
 ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the