



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26790
 Promised Date: 30 MAR 26



WO #: 26790 (Appointment Date: 30 MAR 2026 - Time: 10:00am)

Customer: 92180 - BOURGEOIS, KIRK
 Address: 127 CHIPMUNK HOLLOW WAY
 NEWPORT, TN
 38

Home Phone: (423) 237-8828

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11106

Stock Desc: (11106) 2025 FOREST RIVER
 SANDPIPER 3900HBLR

Model: 3900HBLR

Serial #: 4X4FSAR28SJ048285

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 26 SEP 25

Date In: 04 MAR 26

Promise Date: 30 MAR 26

Promise Time: 09:00am

Schedule Date:

Completed: 27 MAY 26

Warr. Date: 26 SEP 25

Job #1 - External

SC TO TURTLE ROCK LOT 102 (TRY)
 100.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR LEAKING AT VERY BOTTOM
 NEED PROOF OF LEAK, AND DOOR TAG

CAUSE: TECH FOUND THE ENTRY DOOR NOT CLOSING ALL THE WAY AND LEAVING A GAP IN DOOR.

CORRECTION: ADJUST ENTRY DOOR TO CORRECT POSITION
 LABOR .50

Labor

Job #	Description	Hours	Total
2	ADJUSTED ENTRY DOOR	0.30	52.50
Subtotal for Job #2:			52.50

Job #3 - Warranty

BLACK TANK #2 HANDLE IS BENT

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DS BIG COMPARTMENT DOOR LEAKING AND ALLOWING WATER TO ENTER THE COMPARTMENT AREA

CAUSE: RUBBER DOOR SEAL DAMAGED FROM THE LOCK STRIKER, THIS IS ALLOWING WATER IN THE COMPARTMENT AREA.

CORRECTION: REMOVE CURRENT COMPARTMENT DOOR SEAL, CLEAN AREA, REPLACE WITH NEW SEAL AND WATER TEST. NEED TO ADJUST LOCK TO PREVENT NEW SEAL FROM BEING DAMAGED AGAIN.
 LABOR .75

Customer #: 92180
 BOURGEOIS, KIRK





Labor				
Job #	Description	Hours	Total	
4	REPLACED COMPARTMENT DOOR SEAL	0.50	87.50	

Parts				
Part #	Description	Qty	Price	Total
F100338980	SEAL, FOR COMPARTMENT DOOR, INSIDE .36 X .500 D, 3/8" (1500FT) LIPPERT 2021024130	1.00	3.09	3.09

Subtotal for Job #4: 90.59

Job #5 - Warranty

PHOTO OF THE CEILING TRIM THAT WAS FIXED PRIOR

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUST REMOVED STICKER PUT ON AT THE FACTORY AND PEELED THE DOOR PAPER OFF

CAUSE: FACTORY PUT A STICKER ON THE BATHROOM DOOR AND WHEN CUST REMOVED IT THE DOOR OVERLAY PEELED OFF

CORRECTION: REMOVE AND REPLACE THE BATHROOM DOOR
 LABOR .50

Labor				
Job #	Description	Hours	Total	
6	REPLACED BATHROOM DOOR	0.50	87.50	

Parts				
Part #	Description	Qty	Price	Total
F100644365	DOOR 24"X74"	1.00	155.53	155.53

Other Services				
Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	237.28	237.28
CRA	CRATE CHARGES	1.00	50.00	50.00

Subtotal for Job #6: 530.31

Job #7 - Warranty

COMPLAINT: LOWER FRIDGE DOOR IS DRAGGING
 PLEASE GET THE TAG SERIAL AND MODEL BOTH (JPS)

CAUSE: LEFT SIDE FRIDGE DOOR IS HANGING CROOKED AND NOT CLOSING PROPERLY

CORRECTION: NEED DOOR INSERTS AND LOWER ARM TO CORRECT CONCERN
 LABOR 1.0

Labor				
Job #	Description	Hours	Total	
7	INSTALLED DOOR INSERTS	0.50	87.50	

Parts				
Part #	Description	Qty	Price	Total
2023001034	DOOR HINGE	1.00	11.78	11.78

Other Services				
Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	13.69	13.69

Subtotal for Job #7: 112.97





Job #8 - Warranty

COMPLAINT: SMALL DRESSER DRAWERS IN BEDROOM WILL NOT CLOSE

CAUSE: ALL THE DRAWERS IN THE SMALL DRESSER WILL NOT CLOSE CORRECTLY
 TRACKS AND RAILS ARE MISSING BEARINGS AND THE SCREW HOLES ARE STRIPPED OUT

CORRECTION:
 NEED TO REPLACE ALL HARDWARE ON ALL 4 DRAWERS
 LABOR ON ALL 4: 2.0

Labor

Job #	Description	Hours	Total
8	REPLACED HARDWARE ON ALL FOUR DRAWERS	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
F100615925	DRAWER GUIDE, 10" 75# SOFT CLOSE - CABINET	8.00	3.13	25.04
F100615950	DRAWER GUIDE, 10" 75# SOFT CLOSE - DRAWER	8.00	1.03	8.24

Subtotal for Job #8: 208.28

Job #9 - Warranty

COMPLAINT: ONE BLIND IN LIVING AREA AT SEATING HAS A PIN HOLE THAT HAS DEVELOPED
 WILL NEED THE TAG ON THE TOP OF THE SHADE

CAUSE: A SMALL PIN HOLE HAS DEVELOPED ON THE MATERIAL OF THE SHADE, MATERIAL IS
 VERY THIN IN THIS AREA. FAULTY MATERIAL

CORRECTION: REMOVE CURRENT SHADE AND REPLACE WITH NEW ONE
 LABOR .50

Labor

Job #	Description	Hours	Total
9	REPLACED SHADE	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100517815	ROLLER SHADE, 74 X 37 BLACK BAMBOO / FRB53N74X37	1.00	101.67	101.67

Subtotal for Job #9: 136.67

Job #10 - Warranty

NEED THE TAG PHOTO AND OVERALL OF BLIND THAT WAS ADJUSTED

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: TOILET IS LEAKING WILL NEED CLEAR PHOTO OF TAG
 CUST SAID IT WAS OVER FLOWING

CAUSE: WATER VALVE IS NOT CLOSING ALL THE WAY AND ALLOWING A SMALL TRICKLE OF
 WATER TO PASS THROUGH
 THIS IS CAUSING THE TOILET TO EVENTUALLY OVER FILL

CORRECTION: REMOVE AND REPLACE WATER VALVE TO CORRECT ISSUE, THEN TEST
 LABOR WITH DIAG .75

Labor

Job #	Description	Hours	Total
11	REPLACED VALVE	0.75	131.25



Parts

Part #	Description	Qty	Price	Total
60P14281A	DOMETIC WATER VALVE 385311641	1.00	72.83	72.83

Subtotal for Job #11: 204.08

Parts Total: 378.18
Labour Total: 656.25
Sublet Total: 0.00
Extras Total: 300.97

WORK ORDER TOTAL: 1,335.40

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 27 May 2026

Customer Signature : _____

Customer Work Order

W/O: 26790
Promised Date: 30 MAR 26



Customer #: 92180
BOURGEOIS, KIRK

