



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26880



WO #: 26880

Customer: 78701 - STEBBINS, JAYSON
Address:

Home Phone: 802-497-4820

Work Phone:

Author: SPD

Location: IH

Invoice #:

Stock #:
Stock Desc:
Model:
Serial #:
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 24 MAR 26
Promise Date:
Promise Time:
Schedule Date:
Completed: 07 MAY 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER PURCHASED AC MARCH OF 2026 UPON INSTALL THE AC FAILED TO OPERATE

CAUSE: During first initial test after install the fan started to speed up and technician heard a ticking noise and as he turned ac off to inspect the noise there was a bang noise and the ac suddenly stopped. Tech turned the breaker off and removed the shroud up top to inspect the ac and found a insulation blanket wrapped around the condensor fan which was now missing a blade and the condensor coil now has a large dent in it. The insulation blanket was pulled out and the missing fan blade was located in the right rear of the unit.

CORRECTION: REMOVE AND REPLACE A/C AND TEST
LABOR WITH DIAG 2.0

Labor

Job #	Description	Hours	Total
1	REPLACED AC AND TESTED	2.00	350.00

Parts

Part #	Description	Qty	Price	Total
2024039645	FURRION AC 18K WHT DUCTED	1.00	1,303.99	1,303.99

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	180.86	180.86
NII	DISPOSAL	1.00	100.00	100.00

Subtotal for Job #1: 1,934.85

Parts Total:	1,303.99
Labour Total:	350.00
Sublet Total:	0.00
Extras Total:	280.86
WORK ORDER TOTAL:	1,934.85

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 78701
STEBBINS, JAYSON



Customer Signature : _____

Date: 07 May 2026

W/O: 26880

Customer Work
Order



Customer #: 78701
STEBBINS, JAYSON

