

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13179

Date In:	09 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	9666
:	:	Year:	2020
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	MOMENTUM M-CLASS
:	MIDDLEBURY, IN	Model:	381M
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 1/9- CMR PUT A MAS
Purchased Date:	06 NOV 19	:	:
Delivery Date:	29 FEB 20	:	:
InService Date:	:	:	:
Serial#:	573FM4536L1116061	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - CSC - VISUAL              W    1020    GRAND
          INSPECTION FOR MOMENTUM AND SOLITUDE
          UPPER DECK WALL SECUREMENT
          CAUSE:      Service campaign. There are two panels
                     on the inside that are damaged at the
                     bottom but the damage can be covered by
                     baton strips. found cracks in the frame
                     that will need to be repaired- will also
                     need to install lag bolts.
          CORRECTION: ... visual inspection complete.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CSC - 920018 - TO        W    1020    GRAND
          COMPLETE REPAIR FOR CAMPAIGN
          CAUSE:      need to install lag bolts and have the
                     frame repaired due to cracks. There is a
                     crack on the main lower beam on the ds
                     of the bulk head on the bottom-
          CORRECTION: REQUEST: 5.9  customer satisfaction
                     program
RI      COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF        I    PD      GOODW
          REPAIR IS NEEDED.
          CAUSE:      1001 CUSTOMER REQUESTED There are a few
                     pin holes in the dicor. One tube of
                     dicor. Next to the middle a/c the
                     decking has some strange bubbling going
                     on. I don't see any punctures in the
                     membrane and the decking isnt soft. It
                     almost seems like puddles of glue under
                     the membrane. We will just have to keep
```

Continued on page 2

Work Order : 13179

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                an eye on it to see if anything changes.
CORRECTION: ...
1      ROOF RESEAL                      E      1808      GIESE
WARR   COMPLAINT:  WARRANTY REPAIR 3 - WALL REPAIR FROM      W      1020      GRAND
                                CAMPAIGN DAMAGES.
CAUSE:      There are two panels on the inside that
                                are damaged at the bottom but the damage
                                can be covered by baton strips.
CORRECTION: ... REQUEST 2.0 -
2      SUBLET - CRANKY JAKE MOBILE WELDING                    W      1020      GRAND

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 8220961661    BOLT 1/2 - 6 X 3 - 1/2"    W-1020      6      1.05      6.30
WARR0 822061671     BOLT 1/2 -6 x 5 HEX LAG    W-1020      6      1.98     11.88
WARR0 822061052     SEALANT SIKAFLEX 252 WHI    W-1020      1     30.03     30.03
1      677917009213  DICOR SELF LEVELING LAP    E-1808      0     12.80      0.00

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK    W-1020      0.50     140.00     70.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK    W-1020      0.00     140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR        W-1020      0.00     140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK    W-1020      0.00     140.00      0.00
ARR02 WARR      MANUFACTURER WARRANTY        W-1020      0.00     140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK    W-1020      0.85     140.00    119.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK    W-1020      1.71     140.00    239.40
  RI  Z991      PREFORM ROOF INSPECTIO JGK    I-PD        0.30      70.00     21.00
  RI  Z991      PREFORM ROOF INSPECTIO JGK    I-PD        0.00      70.00      0.00
  1  Z990      MISC LABOUR CODE (EXTE        E-1808      0.00     140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR        W-1020      0.00     140.00      0.00
ARR03 RV30G-3    MOLDING R&R FLAT/CORNE        W-1020      0.00     140.00      0.00

```

```

*****
Job #  Sublet Description      SUBLET      bill to      Vendor      Total
*****
  2  CRANKY JAKE WELDING        W-1020     1763-CRANKY JA      0.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR02 FRT          FREIGHT        W-1020      1.00     16.01     16.01
ARR02 FRT          FREIGHT        W-1020      1.00     17.41     17.41
  1  SSE          SHOP SUPPLIES - EXTERNAL    E-1808      1.00      0.00      0.00

```

Continued on page 3

Work Order : 13179

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PD	0.00	21.00	0.00	0.00	0.00	21.00
W	1020	48.21	428.40	0.00	33.42	0.00	510.03
	Totals	48.21	449.40	0.00	33.42	0.00	531.03

&k2S
&k0S