



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26880



WO #: 26880

Customer: 78701 - STEBBINS, JAYSON
Address:

Home Phone: 802-497-4820

Work Phone:

Author: TC

Location: IH

Invoice #:

Stock #:
Stock Desc:
Model:
Serial #:
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 24 MAR 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER PURCHASED AC MARCH OF 2026 UPON INSTALL THE AC FAILED TO OPERATE

CAUSE: During first initial test after install the fan started to speed up and technician heard a ticking noise and as he turned ac off to inspect the noise there was a bang noise and the ac suddenly stopped. Tech turned the breaker off and removed the shroud up top to inspect the ac and found a insulation blanket wrapped around the condensor fan which was now missing a blade and the condensor coil now has a large dent in it. The insulation blanket was pulled out and the missing fan blade was located in the right rear of the unit.

CORRECTION: REMOVE AND REPLACE A/C AND TEST
LABOR WITH DIAG 2.5

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 78701
STEBBINS, JAYSON



Customer Signature : _____

Date: 24 Mar 2026

