

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13228

Date In:	17 FEB 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11227
:	:	Year:	2025
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE XLS
:	MIDDLEBURY, IN	Model:	23LDE
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:	16 APR 25	:	:
Delivery Date:	08 MAY 25	:	:
InService Date:		:	:
Serial#:	573TE282XS3440902	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT: BEARING REPACK - CMR REQUESTS THAT THEY E    15106 FEUER
      ARE JUST DONE AS THEY ARE TAKING ON A
      LONG TRIP.
      CAUSE: repack all 4 bearings
      CORRECTION: removal of tires and hubs from axles i
      also inspected bearings ok repack
      bearings with new grease and hub seals
      installed all 4 hubs and torqued tires
      to spec
RI     COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF      I    PD    GOODW
      REPAIR IS NEEDED.
      CAUSE: roof inspection
      CORRECTION: roof inspection was done all vents and
      sealants are ok
WARR  COMPLAINT: WARRANTY REPAIR 1 - FENDER SKIRTS HAVE      W    1020  GRAND
      SOME CRACKING
      CAUSE: pics and measurements taken on door side
      fender skirt is cracked
      CORRECTION: will need a new fender skirt.....
      request: 1.0
2      COMPLAINT: THE NEWLY INSTALLED SHADE HAS CAPS ON      W    1020  GRAND
      THE BOTTOM SECTION TO KEEP METALL INSIDE
      AND NONE OF THE OTEHR SHADES DO, ARE
      THEY SUPPOSED TO BE CAPPED OLIKE THAT?
      AND IF SO CAN WE GET THE CAPS TO REPLACE
      THEM?
      CAUSE: inspection of all shades the newly shade
      that was installed the aluminum flap rod
*****
```

Continued on page 2

Work Order : 13228

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                that in in was cut to exact size so you
                can installed cap but all other shade
                the aluminum flap rods are cut short
                intentionally so you cant install caps
                ot get cut.  unless the manufacturer can
                send us aluminum fat rods and end caps
                we can cut to size measurements and pics
                taken
CORRECTION: inspection of all shades will need 3 new
                shades with end caps ... request: .5

```

```

*****
Job # Part No      Description           PARTS      Bill to  Qty   Price   Total
*****
1      030999740786 2pk TEKONSHA GREASE SEAL E-15106      2     12.18   24.36

```

```

*****
Job# Lab Code  Description           LABOUR  Mech Bill to  Hrs   Rate   Total
*****
1 R735        BEARINGS, PACK (TANDEM JS  E-15106  1.14  130.00  148.20
RI Z991        PREFORM ROOF INSPECTIO JS  I-PD     0.30  70.00   21.00
ARR01 Z992        MISC LABOUR CODE (WARR JS  W-1020   0.50  140.00  70.00
2 Z992        MISC LABOUR CODE (WARR JS  W-1020   0.50  140.00  70.00
1 R735        BEARINGS, PACK (TANDEM JS  E-15106  1.60  130.00  208.00
1 R735        BEARINGS, PACK (TANDEM JS  E-15106  0.26  130.00  33.80
ARR01 RV30L-2  FENDERSKIRT R&R TANDEM     W-1020   0.00  140.00  0.00

```

```

*****
Job # Excode      Description           EXTRAS      bill to  Qty   Price   Total
*****
1 SSE          SHOP SUPPLIES - EXTERNAL  E-15106  1.00  29.25   29.25

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E 15106           24.36      390.00      0.00      29.25      24.43      468.04
I PD              0.00      21.00      0.00      0.00      0.00      21.00
W 1020            0.00      140.00      0.00      0.00      0.00      140.00

Totals           24.36      551.00      0.00      29.25      24.43      629.04

```

&k2S
&k0S