



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26914



WO #: 26914 (Appointment Date: 01 APR 2026 - Time: 09:00am)

Customer: 92645 - WILLIS, JANET
Address: 1845 BAYS MOUNTAIN RD
NEW MARKET, TN
37820

Home Phone: (810) 577-0053

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10925

Stock Desc: (10925) 2024 FOREST RIVER
FORESTER 3051SF

Model: 3051SF

Serial #: 1FDXE4FN2SDD01919

Chassis #: 1FDXE4FN2SDD01919

Mileage: 100

Key #: 6999

Req'n #:

License #:

Trim:

Purchase Date: 12 APR 25

Date In: 01 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 12 APR 25

Job #1 - Warranty

COMPLAINT: FRIDGE CAME OFF WHEN CUSTOMER OPENED IT AND THE DOOR FELL ON CUSTOMERS FOOT AND PUT A HOLE IN THE FLOOR

CAUSE: CUST STATED HE OPENED THE UPPER FRIDGE DOOR AND IT CAME OFF. WHEN THE DOOR CAME OFF IT HIT THE CUSTOMERS TOE AND CAUSED A HOLE IN THE FLOORING AT FRIDGE. THIS ALSO DAMAGED THE FRIDGE DOOR ON THE BOTTOM CORNER WHEN IT CAME OFF AND HIT THE CUSTOMER AND FLOOR

CORRECTION: REPLACE THE UPPER FRIDGE DOOR AND HARDWARE
LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR SLIDE SEAL IS COMING OFF THE UNIT

CAUSE: INTERIOR REAR BALL SEAL IS COMING OFF THE TRACK

CORRECTION: REINSERT SEAL TO CORRECT ISSUE
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: AUTO LEVEL PUSH PAD IS GIVING CUST ISSUES HE STATED HE HAS TO PUSH IT VERY HARD TO GET IT TO WORK

CORRECTION: PUSH PAD WORKED AS DESIGNED
WARRANTY HAD 2 TECHS VERIFY THIS. YOU HAVE TO PUSH THE VERY CENTER OF THE BUTTONS

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: USB PLUG ABOVE DINETTE DOES NOT WORK

CAUSE: VOLTAGE TO THE USB PORT IS GOOD, USB HAS FAILED OUT AND IS NOT WORKING

CORRECTION: REPLACE THE USB PORT AND TEST
LABOR .30

Customer #: 92645
WILLIS, JANET



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BROWN SPOTS ARE SHOWING UP ON THE CEILING, THIS IS PLACES IN THE WHOLE UNIT CUST STATED

CAUSE: CUST STATED THERE IS BROWN SPOTS THAT ARE APPEARING ON THE CEILING

CORRECTION: SPOTS NEED TO BE CLEANED OFF THEN COLOR BLEND AREA IF NEEDED
LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: LEFT FRONT AND RIGHT REAR JACK WOULD NOT COME UP FOR CUSTOMER
FLASHED CONTACT LCI

CUST IS HAVING TO REBOOT EACH TIME THIS IS A ON GOING ISSUE

CORRECTION: 2 TECHS COULD NOT DUPLICATE THIS ISSUE

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: WHEN HE HOOKS WATER TO CITY CONNECTION OR THE FLUSH TANK BOTH OF THESE ARE LEAKING ON THE BACK SIDE

CORRECTION: CUST HAS QUICK CONNECTS ON THESE AND THE TECH REMOVED THEM,
HOOKED TO OUR WATER AND NO LEAKS WERE FOUND AT THIS TIME

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CS THAT THE AWNING COMES IN REAL SLOW GOES OUT JUST FINE

CORRECTION: AWNING IS GOING IN AND OUT WITH NO ISSUES
WARRANTY VERIFIED

Subtotal for Job #8: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Apr 2026

W/O: 26914



Customer #: 92645
WILLIS, JANET

