



RECREATIONAL VEHICLES

Claim CLAIM5824 (KZ0042779)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth Dealer	Repairing dealer name	Labor rate	Changed warranty		Date of Purchase
								rate	Type	
CLAIM5824 (KZ0042779)	27257	6/4/2026	1/1/0001	4EZTL2821V4053472	CUST-002602	TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Pre-delivery	1/1/0001

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	2551_01_B	compartment door (Lippert) - Damaged - Replace Complaint Door side compartment door has chips on the inside, small holes Cause Noted on DAF Correction Replace compartment door and reseal area if needed	0.5	0.5	87.5	0	1	0.5	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5514_03_A	R/R Trim, 8' piece - Improperly Installed - Repair/adjust/tighten Complaint Slider out stile has several nail holes across it Cause Noted on DAF, nail holes not filled or blended at build Correction Fill, color, and blend area	0.2	0.1	17.5	0	1	0.1	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5540_02_A	Repair, General, Putty, Clean, Sand, Etc. - Delam/Peeling/Flaking - Repair/adjust/tighten Complaint Paint faded across the top of bench seating Cause Noted on DAF Correction Fill, color, and blend area	0.5	0.5	87.5	0	1	0.1	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5592_03_A	R/R Cabinet Latch - Improperly Installed - Repair/adjust/tighten Complaint Kitchen cabinets above the sink don't shut all the way on one side Cause Noted on DAF Correction Adjust hinge on door to open and close correctly	0.3	0.1	17.5	0	1	0.1	Approved



RECREATIONAL VEHICLES

Claim CLAIM5824 (KZ0042779)

Last Modified By

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged -	Repair/adjust/tighten	0.3	0	0	0	1 0.1	Denied
Complaint Brown stains on the ceiling as you enter the unit Cause Noted on DAF Correction Clean spots and color blend if needed								

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
6607_03_A	R/R Valance Bracket - Improperly Installed -	Repair/adjust/tighten	0.2	0.1	17.5	0	1 0.1	Approved
Complaint Hall valance is loose on the wall in hallway area Cause Noted on DAF Correction Resecure valance back in place correctly								

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged -	Repair/adjust/tighten	0.2	0	0	0	1 0.1	Denied
Complaint Stile above bedroom door has a chipped spot Cause Noted on DAF Correction Fill, color, and blend to match								

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
5545_01_B	R/R DOOR(S),SLIDING - ALL - Damaged - Replace		0.5	0.5	87.5	0	1 0.5	Approved
Complaint Bedroom door is damaged at the top in 2 places Cause Noted on DAF, damaged at factory install Correction Replace the bedroom door								

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	472.50	Approved labor & subLet	315.00
Submitted freight	0.00	Approved freight	0.00
Total Submitted	<u>472.50</u>	Total approved	<u>315.00</u>