



RECREATIONAL VEHICLES

Claim CLAIM5927 (KZ0042908)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth Dealer	Repairing dealer name	Labor rate	Changed warranty		Date of Purchase
								rate	Type	
CLAIM5927 (KZ0042908)	27263	6/5/2026	1/1/0001	4EZTL3120V4053771	CUST-002602	TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Pre-delivery	1/1/0001

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5506_03_A	Repair Linoleum - Improperly Installed - Repair/adjust/tighten	2	2	350	0	1	0	Denied
		Complaint Floor in front of the stove squeaks and goes down more than normal in a spot Cause Not braced underneath and allowing the floor to go down. Noted on DAF Correction Need to add a brace under the floor to stabilize floor							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5546_01_B	R/R Door(s), Swinging - All - Damaged - Replace	0.5	0.3	52.5	0	1	0.3	Approved
		Complaint Main bathroom door is damaged at the bottom and chipped up from that Cause Noted on DAF Correction Replace door							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged - Repair/adjust/tighten	0.2	0.7	122.5	0	1	0.1	Approved
		Complaint Trim above bunk door is scratched Cause Noted on DAF Correction Fill, color, and blend area							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5545_01_B	R/R DOOR(S),SLIDING - ALL - Damaged - Replace	0.5	0.5	87.5	0	1	0.5	Approved
		Complaint Bunk room door damaged on one side, this is very deep and a large area. Door also has several scratches on it Cause Noted on DAF Correction Replace door							



RECREATIONAL VEHICLES

Claim CLAIM5927 (KZ0042908)

Last Modified By

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged -	Repair/adjust/tighten	0.5	0	0	0 1	0.1	Denied
	Complaint	Main bedroom door is scratched/damaged in several areas						
	Cause	Noted on DAF						
	Correction	Fill, color, and blend area						

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
2368_06_B	R/R Door Bumpers - Part Missing - Replace		0.1	0.1	17.5	0 1	0.1	Approved
	Complaint	Missing bumper plug/cover						
	Cause	Noted on DAF						
	Correction	Replace bumper plug						

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged -	Repair/adjust/tighten	0.2	0	0	0 1	0.1	Denied
	Complaint	Chips in the cabinet door above tv						
	Cause	Noted on DAF						
	Correction	Fill, color, and blend area						

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	700.00	Approved labor & subLet	280.00
Submitted freight	0.00	Approved freight	0.00
Total Submitted	<u>700.00</u>	Total approved	<u>280.00</u>