

Pre-Authorization

Pre-Authorization number PA03016480 Reference no: 66186 Status: Approved Approved by papca Approved date 1/5/2022
 Servicing Name Address VIN Retail sold on Dealer

1194	Basden's American RV			Basden's American RV 600 E Baseline Rd Evansville, IN 47725		4YDFCGS27N2503252			
Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3200114A	Door - Interior Hin	0.00	0.30	0.20		1	0.20	Complaint:BATHROOM DOOR NEEDS ADJ Cause:INSTALLED WRONG Correction:adjusted the screws on the door KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	5104216A	Receptacle - 12V	0.00	0.60	0.20		1	0.20	Complaint:WIRES HANGING OUT OF BOTTOM OF COUCH Cause:WIRES HANGING UP Correction:removed the bottom of couch to get to the wires then ziptied them and put the couch back together KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
3	5104303A	Receptacle - 120\	0.00	0.50	0.10		1	0.20	Complaint:50 AMP 120V PLUG IS MISSING COVER Cause:MISSING COVER Correction:INSTALL NEW COVER KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
4	3300528A	Blind - Vertical - R	0.00	0.80	0.40		1	0.20	Complaint:BLIND ABOVE TABLE WILL NOT CLOSE ALL THE WAY Cause:INSTALLED THE WRONG BLIND Correction:INSTALL THE CORRECT BLIND KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
5	2302326B	Compartment Doc	0.00	0.30	0.20		1	0.20	Complaint:FR COMPARTMENT DOOR WONT LATCH Cause:NEED TO ADJ Correction:added shims and moved striker plate door works as should KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
6	3401016A	Towel Ring or Bar	0.00	0.30	0.10		1	0.10	Complaint:TOWEL RACK IN BATHROOM NEEDS FIX

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company

Pre-Authorization

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
									Cause:TOWEL RACK IS LOOSE Correction:moved screws till it held KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
Pre-Authorization number PA03016480					1.20				

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company