



GE APPLIANCES
a Haier company



Product Support Form

For Technical Assistance Call: 800-772-7262

OEM Claims Email: RecreationalLiving-warranty@geappliances.com

Dealer Claims Email: NTRemergingResources@geappliances.com

VEHICLE

Manufacturer: Forest River
Model Year: 2025
Make: Forester
Model: 3251
Complete Vin: 1FDXE4FN4SDD19466
Manufacturer Claim #: 00258654
Manufacturer PO #: 27255

DEALER OR SERVICER

Dealer Name: Triam RV Center
Dealer Account #: 7759
Dealer Contact: Stephanie
Dealer Contact Phone: 423-235-1167
Dealer Contact E-mail: tnwarranty@triamrv.com
Dealer Repair/Work Order #: 27255
Dealer PO #: 27255
Dealer Ship-To Address: 1202 Idell Road
City: Bulls Gap State: TN ZIP: 37711

OWNER

Owner Name: William Harold Davis
Owner Phone: 423-608-5103
Owner E-mail: NA
Owner Address: 3363 Salem Road
City: Parrottsville State: TN ZIP: 37843

DEALER OR SERVICER

Model Number: ARH15AACBL2
Serial Number: RV1000G29R
Date of Purchase: 3-22-2025
If Air Conditioner, Type of Controls:
 GE Single Zone Thermostat Black White
 Firefly Integrations Lippert One Control
Other:

Describe the problem. Include complaint, cause and correction, if known:

A/C not cooling
Determined A/C Compressor has Low Amps
Replace A/C

When requesting complete product replacement, please provide the following information:

ROOFTOP AIR CONDITIONER/ HEAT PUMP

Visible Leak? (Y/N):
Compressor Running? (Y/N):
AC Amp Draw Black Compressor Wire: 9.1 Amps
Ambient Roof Temperature: 88
Return/Intake Temperature: 91
Discharge/Output Temperature: 89

REFRIGERATOR (12-VOLT DC MODELS ONLY)

Visible Leak? (Y/N):
Compressor Running? (Y/N):
DC Amp Draw (12VDC line):
DC Volts:
DC Supply Wiring Gauge: _____ Length: _____
of Fault LED Flashes:
Fresh food warm/freezer cold with frost? (Y/N):
Frost pattern in fresh food section (choose one):
 No frost Half-way Full frost
Vehicle Interior Temperature:
Fresh Food Temperature (after 2 hrs.):
Freezer Temperature (after 2 hrs.):