



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26977



WO #: 26977

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11297

Stock Desc: 2026 TT KEYSTONE BULLET 245RKS

Model: 245RKS

Serial #: 4YDTBLL22TD431682

Chassis #:

Mileage: 0

Key #:

Req'n #: 62743

License #:

Trim:

Purchase Date: 29 MAY 26

Date In: 10 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 11 JUN 26

Warr. Date: 29 MAY 26

Job #1 - Warranty

COMPLAINT: the 2nd drawer down from from top to the left of entry is damaged and rough

CAUSE: noted on daf
wood damaged when built

CORRECTION: remove drawer and guides, replace with new drawer and reinstall guides then test drawer
labor .60

Labor

Job #	Description	Hours	Total
1	REPALCED FACE OF DRAWER	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
767760	CABINET 6X14	1.00	23.99	23.99

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	22.74	22.74

Subtotal for Job #1: 99.23

Job #2 - Warranty

COMPLAINT: cabinetry above 2nd drawer in kitchen is damaged

CAUSE: wood is rough and looks damaged on cabinetry door
noted on daf

CORRECTION: remove the damaged cabintery stile and replace with new
labor .50

Labor

Job #	Description	Hours	Total
2	REPLACED STILE	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
738553	STILE 2"X96"	1.00	10.08	10.08

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	51.57	51.57

Subtotal for Job #2: 149.15

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Job #3 - Warranty

COMPLAINT: top cabinet door 1st on left at entry door has a defective area

CAUSE: damaged at factory instll
noted on dafCORRECTION: smooth area on cabinet door, fill, color blend area
labor .40**Labor**

Job #	Description	Hours	Total
3	SMOOTH COLOR AND BLEND	0.30	52.50

Subtotal for Job #3: 52.50**Job #4 - Warranty**

COMPLAINT: 2nd cabinet door at entry is cracked

CAUSE: noted on daf

CORRECTION: remove damaged cabinet door and the hardware, replace cabinet door with new one and
reinstall hardware
labor .50**Labor**

Job #	Description	Hours	Total
4	REPALCED	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
776422	CABINET DOOR 12.5X21.5	1.00	63.90	63.90

Subtotal for Job #4: 116.40**Job #5 - Warranty**

COMPLAINT: left side of slide out fascia is scratched and paint faded in spots

CAUSE: noted on daf

CORRECTION: fill, color and blend areas
labor .40**Labor**

Job #	Description	Hours	Total
5	FILL AND COLOR	0.30	52.50

Subtotal for Job #5: 52.50**Job #6 - Warranty**

COMPLAINT: bathroom door from the living area has scratched paint in several areas

CAUSE: noted on daf

CORRECTION: fill, color and blend areas
labor .40**Labor**

Job #	Description	Hours	Total
6	FILL AND COLOR	0.30	52.50

Subtotal for Job #6: 52.50Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 26977

Parts Total:	97.97
Labour Total:	350.00
Sublet Total:	0.00
Extras Total:	74.31
WORK ORDER TOTAL:	522.28

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 11 Jun 2026

Customer Signature : _____



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

