

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 1054928		CLAIM STATUS Paid	
LINK FORD & RV MINONG LLC		CLAIM 2697432	
1025 W HOKAH ST		CLAIM ORIGIN WEB	
MINONG, WI 54859		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC6TG815500
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16RBX-452
LARRY FORD		DEALER RO #	40772
302 WEST HAZEL ST		CLAIM START DATE	06/03/2026
Spooner, WI 54801		CLAIM END DATE	06/04/2026
USA			
Retail Date of Purchase	05/20/2026	WARRANTY EXPIRATION DATE	05/20/2027

Claim Line Details

Labor

Line# 1	Operation Code 60-141-24-00-001593	Operational Description Tub Pan - Plumbing/Shower, Tub Surround/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : alix@dealer-advisors.com, 2026-06-03 12:57:41 :: Complaint: Customer states when they run water, the shower basin filled up. Cause: Removed drain screen from shower to check for obstruction, found nothing. Grey tank was empty, ran kitchen sink, bathroom sink, and shower until grey tank was full, the shower basin did not fill up. Correction: Shower drains as it should based of testing/diagnosing. Dumped grey tank since it filled while testing.			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$165.00	
Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00	
	Notes Denied, this is not a warranty issue. There was no issue, there was no correction. This is not covered under warranty. Denied, Forest River respectfully denies warranty and goodwill participation in this repair to this unit. Dp			

Labor

Line# 2

Operation Code

60-141-01-00-001583

Operational Description

Interior Shower Head & Hose (Read Notes!!!) - Plumbing/Shower, Tub Surround/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : alix@dealer-advisors.com, 2026-06-03 13:01:29 :: Complaint: Customer states the shower head has very low water pressure. Cause: Debris in showerhead Correction: Took shower head off, cleaned a little bit of debris out of screen, put back on and tested. Pressure seems normal, there is a small rubber "o" ring in there that could be removed. I tried it both ways, seems like it was about the same with or without the O ring in there. Left it in place.

Model#

Dlr Sub Hrs

0.40

Sub Labor Amt \$66.00

Serial#

Appr Hrs

0.30

Appr Labor Amt \$49.50

Notes

The time requested is excessive for this repair, time adjusted. NVCB .30 to clean the debris from the shower head. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Labor

Line# 3	Operation Code 60-141-01-00-001577	Operational Description Tub Faucet with Shower Diverter - Plumbing/Shower, Tub Surround/Replace/No Tread Code		
Complaint, Cause, Correction Original Note : alix@dealer-advisors.com, 2026-06-03 13:02:38 :: Complaint: Customer states the hot and cold shower handles are reversed. Cause: Installed incorrectly. Correction: Hot was on the right and cold was on the left, swapped handles. Tested and hot works for hot and cold works for cold. Added before and after photos.				
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$82.50

Appr Labor Amt \$82.50

The time requested is excessive for this repair, time adjusted. The knobs did not be removed to switch. NVCB .10 to switch the popout hot and cold inserts for the shower faucet handles. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp
Changed to the correct code. Dp.
Dp.

Submitted	Labor Amt	\$313.50	Approved	Labor Amt	\$132.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$313.50		Total	\$132.00

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.