

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 1054928
 LINK FORD & RV MINONG LLC
 1025 W HOKAH ST
 MINONG, WI 54859
 USA

CLAIM STATUS Paid
 CLAIM 2692580
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2LC9B8TG012140
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 015 / 015G
 ITEM # LCT44PARK-15G
 DEALER RO # 40256
 CLAIM START DATE 05/29/2026
 CLAIM END DATE 06/02/2026

Labor rate: \$165.00

OWNER INFORMATION

ANTHONY SCHILLING
 6618 S CTY RD B
 South Range, WI 54874
 USA

Retail Date of Purchase 05/01/2026 WARRANTY EXPIRATION DATE 05/01/2027

Claim Line Details

Labor

Line# 1 Operation Code 20-78-01-00-000799 Operational Description Awning Fabric - Lippert - Exterior/Awnings (Lippert)/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : alix@dealer-advisors.com, 2026-05-29 14:22:14 :: Previous 2633491 paid and part markup was not paid for no cost part markup. This is for markup only. Complaint: Dealer states the fabric on second awning has small tear above the entry door. Cause: factory rip. Correction: Needs new fabric.

Model# 1	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial# 1	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

This is being authorized for the part markup from claim #2633491. NVCB MUA Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1	Item #	Description
	USERPART	F100838760 - awning fabric 14' white universal replacement. This is the 30% markup for the no cost part sent to dealership. Instructed by Katlynn Cline to re-enter for payment.
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$58.39
	Appr Qty 1.00	Appr Dlr Price \$58.39
		Part tag
		Sub Freight \$0.00
		Appr Freight \$0.00

Notes

Submitted Labor Amt \$0.00
 Parts & Freight \$58.39
 Total \$58.39

Approved Labor Amt \$0.00
 Parts & Freight \$58.39
 Total \$58.39

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.