

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 66398  
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725  
Phone:  
Stock Number: 11196 - 2022 RETRO 171DRD 59CCC4519NL005120  
VIN: 59CCC4519NL005120 HIN: SER#: 59CCC4519NL005120  
Mileage: 0 Work Order Comp: 30 MAR 22  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 27 JAN 22 Inv #: 374697

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
66398 4 7 WAY DAMAGED  
7 way was dragged on the ground and is damaged.  
removed plate from junction box. removed nuts from wire  
terminals. removed 7 way wires. 7 way wires were installed first  
in this box so i had to remove all other wires and then remove 7  
way wires. removed damaged plug. installed wire terminals on new  
7 way plug. secured 7 way to frame, secured 7 way to junction  
box. installed 7 way wires and all other wires. tightened down  
nuts. tested 7 way and lights. secured panel to junction box  
  
66398 2 SEALER ON WINDOW  
SEALER ON WINDOW  
TOOK A RAG AND MINERAL SPIRITS AND REMOVED SEALER FROM WINDOW  
  
66398 3 SCREEN DOOR HITTING FRAME  
door is hitting the frame  
took a block of wood and moved the top left corner of the frame  
in so the door would stop hitting.  
  
66398 5 FRESH FILL LINE RUNS UPWARD  
FILL LINE FOR FRESH TANK IS RUNNING UP AND IS CAUSING WATER TO  
BACKFEED AND NOT FILL THE TANK.  
REMOVED FILL LINE. REROUTED UNDER OTHER WATER LINES THAT RAN  
THROUGH THE COMPARTMENT AND FLOOR. CUT EXCESS LINE. SECURED LINE  
TO INLET.

66398 6 FRIDGE DOOR HITTING ON THE BOTTOM  
SCREWS ON BOTTOM OF FRAME WERE INSTALLED AT AN AGLE AND WERE  
HITTING THE BOTTOM OF THE DOOR WHEN SHUTTING  
REMOVED ORIGINAL SCREWS. INSTALLED NEW SCREWS FLUSH WITH BOTTOM

66398 7 THE WINDOW OVER THE DINETTE WILL NOT STAY UP.  
WINDOW BLIND WONT STAY UP.  
ADJUSTED TENSION ON BLIND CHORD SO IT WILL STAY UP.

66398 8 THE INSIDE SHROUD FOR THE ROOF VENT IS CRACKED.

| *****    |      |                             |        |  |      |        |       |
|----------|------|-----------------------------|--------|--|------|--------|-------|
| Lab Code | Job# | Description                 | LABOUR |  | Hrs  | Rate   | Total |
| *****    |      |                             |        |  |      |        |       |
| Z990     | 4    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.50 | 150.00 | 75.00 |
| Z990     | 2    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.10 | 150.00 | 15.00 |
| Z990     | 3    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.20 | 150.00 | 30.00 |
| Z990     | 5    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.40 | 150.00 | 60.00 |
| Z990     | 6    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.10 | 150.00 | 15.00 |
| Z990     | 7    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.20 | 150.00 | 30.00 |
| Z990     | 8    | MISC LABOUR CODE (EXTERNAL) |        |  | 0.30 | 150.00 | 45.00 |

>>>>> Claim Total: 319.67

Date: \_\_\_\_\_