

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13671

Date In:	17 JUN 26	Author:	MGRAY
Promised Date:	25 JUN 26	Stock No:	11386
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF MICRO-LITE
:	CHICAGO, IL	Model:	22FBS
Postal/Zip:	60673-1218	Miles/Hrs:	:
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	emailed est 6/18
Purchased Date:	17 MAR 26	:	:
Delivery Date:	24 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TFLX26SD465456	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
1      COMPLAINT:  there is a crack in the in the fresh      W      1021      FORES
        water fill tube about 2 inches down,
        check water system on city and fill tank
        from city look for leaks
        CAUSE:      Fresh tank fill tube is broke
        There is only one way to fill the fresh
        tank and it is the fill tube there is no
        other way I did check for leaks on city
        water and found nothing at this time
        CORRECTION: Will need a new fresh tank tube      $5.00
        foot for fresh water tube. Could use up
        to 10 feet      request:2.5
2      COMPLAINT:  customer states Could you add checking      W      1021      FORES
        the inverter It may have gotten wet due
        to the broken water fill tube. An akarm
        was going off for about 24 hours. Once i
        figured out it was probably the
        inverter, I tried turning off the
        inverter from the panel, but the panel
        looked like it was not working either. I
        finally disconnected the batteries and
        the alarm shut off. I reconnected the
        batteries and everything seems good
        except the inverter control panel still
        seems to be reading jibberish."
        CAUSE:      Cmr got water sprayed on it did not know
        that the fresh tank hose was broken and
        shorted out the inverter had Matt come
```

Continued on page 2

Work Order : 13671

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              look at it too
      CORRECTION: Will need a new inverter have a price
                  attached to work order      request: 2.0

```

```

*****
Job # Part No Description      PARTS      Bill to  Qty      Price      Total
*****
1      EST      WATER FILL TUBE      W-1021      0      32.50      0.00
2      EST      ARTWF-5318 - 1800WATT PURE SI W-1021      0      32.50      0.00

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1  Z990      MISC LABOUR CODE (EXTE JL      W-1021      0.18      140.00      25.20
2  Z990      MISC LABOUR CODE (EXTE JL      W-1021      1.00      140.00      140.00
1  Z990      MISC LABOUR CODE (EXTE JL      W-1021      0.08      140.00      11.20
1  Z990      MISC LABOUR CODE (EXTE JL      W-1021      0.74      140.00      103.60
1  Z990      REPLACE FILL TUBE      W-1021      0.00      140.00      0.00
2  F900      POWER CONVERTER, R & R      W-1021      0.00      140.00      0.00

```

```

*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
1  SSE      SHOP SUPPLIES - EXTERNAL      W-1021      1.00      0.00      0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      0.00      280.00      0.00      0.00      0.00      280.00
      Totals      0.00      280.00      0.00      0.00      0.00      280.00

```

&k2S

&k0S