

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Authorized
MYERS RV CENTER INC		<b>CLAIM</b>	2715671
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT3CSPB3SG128152
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	049 / 049B
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	CSF250RLX
DIANA STOW		<b>DEALER RO #</b>	73542
503 TRUJILLO ST #A		<b>CLAIM START DATE</b>	06/18/2026
Los Lunas, NM 87031		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	06/28/2025	<b>WARRANTY EXPIRATION DATE</b>	06/28/2026

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	20-43-01-00-000589	<b>Operational Description</b>
		Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code
<b>Complaint, Cause, Correction</b>		
Original Note : stephanie@dealer-advisors.com, 2026-06-18 21:29:36 :: Complaint: Customer states there is a bubble on top black strip decal to the left of bedroom window on passenger side Cause: Large bubble in decal Correction: Used a fine need and poked a couple of holes in the decal bubble. Tried to smooth the bubble out, however, the decal has stretched and will no longer lay flat. Recommend replacement of decal.		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	0.50	\$95.00
<b>Serial#</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
	0.50	\$95.00
<b>Notes</b>		
Authed as requested		

### Labor

**Line# 2**

<b>Operation Code</b>	20-43-01-00-000589	<b>Operational Description</b>
		Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code
<b>Complaint, Cause, Correction</b>		
Original Note : stephanie@dealer-advisors.com, 2026-06-18 21:31:14 :: Complaint: Customer states there is a bubble that has popped on black strip above tires on passenger side Cause: Decal has a hole in it due to bubble popping Correction: Recommend the removal and replacement of the decal. Decal is on passenger side that goes from entry door forward to approximately center of the fender skirt.		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	0.50	\$95.00
<b>Serial#</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
	0.50	\$95.00
<b>Notes</b>		
Authed to replace graphic		

<b>Submitted</b>	Labor Amt	\$190.00	<b>Approved</b>	Labor Amt	\$190.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$190.00		Total	\$190.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
All repairs described have been inspected and are satisfactory.