



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26524  
 Promised Date: 05 DEC 25



WO #: 26524 (Appointment Date: 05 DEC 2025 - Time: 09:00am)

Customer: 59745 - MCLAIN, BOBBY  
 Address: 65 LEE SHELTON LN  
 AFTON, TN  
 37616

Home Phone: 423-823-1482

Work Phone:  
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11205  
 Stock Desc: (11205) 2026 DUTCHMEN ASPEN  
 TRAIL 3200WAP  
 Model: 3200WAP  
 Serial #: 4YDTATR26T8920167  
 Chassis #:  
 Mileage:0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date: 11 OCT 25  
 Date In: 05 DEC 25  
 Promise Date: 30 DEC 25  
 Promise Time: 09:00am  
 Schedule Date:  
 Completed: 11 MAR 26  
 Warr. Date: 11 OCT 25

**Job #1 - External**

SC TO R&R CAMP GROUND . CUST STATED TO GO LEFT WHEN YOU ENTER AND YOU WILL NOTICE THAT CAMPER CUST WILL BE THERE

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
<b>Subtotal for Job #1:</b>				<b>0.00</b>

**Job #2 - Warranty**

COMPLAINT: FRIDGE DOES NOT COOL TO DESIRED TEMP. TECH PLEASE GET ALL MODEL AND SERIAL NUMBERS ON FRIDGE TAGS ARE SOMETIMES AT THE BOTTOM (JPS)

CORRECTION: FRIDGE COOLING AS DESIGNED

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: OUTSIDE LEFT SPEAKER DOES NOT WORK.

CAUSE: TECH VERIFIED SPEAKER IS NOT WORKING.SPEAKER TEST GOOD AND THE CONTINUITY IN SPEAKER WIRE FROM RADIO IS GOOD.TESTED SPEAKER AT RADIO WIRE CONNECTION, NO SOUND FROM RADIO ON LEFT SPEAKER. POWER BUTTON IS CROOKED AND NOT OPERATING PROPERLY. (JPS)

CORRECTION: REPLACE RADIO  
 AND DIAG TIME  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
3	REPLACED RADIO	0.50	N/C

**Parts**

Part #	Description	Qty	Price	Total
678702	RADIO BT-BT105	1.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	N/C	N/C
<b>Subtotal for Job #3:</b>				<b>0.00</b>

Customer #: 59745  
 MCLAIN, BOBBY



W/O: 26524  
Promised Date: 30 DEC 25

**Job #4 - Warranty**

COMPLAINT: OUTSIDE CARGO ON RIGHT SIDE UPPER END WILL NOT STAY CLOSED, BARELT CATCHING LIP AT BOTTOM

CAUSE: TECH VERIFIED BOTH LATCHES BARELY MAKING CONNECTION TO HOLD DOOR CLOSED, DOOR CAN EASLIY BE PULLED OFF. ATTEMPTED TO ADJUST DOOR TO LATCHES,SAME RESULTS NO CHANGE IN CONCERN. LATCHES ARE TO HIGH UP ON DOOR TO MAKE PROPER CONNECTION.(JPS)

CORRECTION: REPLACE THE COMPARTMENT DOOR  
LABOR FOR DIAG, ADJUSTMENT AND DOOR REPLACEMENT 1.5

**Labor**

Job #	Description	Hours	Total
4	ADJUSTED DOOR	0.50	N/C

**Subtotal for Job #4: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 13 Apr 2026

Customer #: 59745  
MCLAIN, BOBBY

