

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66870
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 39027 - EDDY WALTER
Address: 939 N PEERLESS RD EVANSVILLE, IN

47712

Phone: 812-589-4633

Stock Number: 11031 - 2021 MONTANA 3231CK 4YDF32321M4704827

VIN: 4YDF32321M4704827 HIN: SER#: 4YDF32321M4704827

Mileage: 0 Work Order Comp: 30 APR 22

Auth. No: Dealer #: 1194

Warr. Date: 28 AUG 21 Work Order Date: 24 MAR 22 Inv #: 376307

WO #	Job #	Description	JOB INFORMATION

66870	3	THE LEFT FRONT BASEMENT DOOR WEATHER STRIP AT THE TOP IS STUCK TO THE DOOR FRAME THE LEFT FRONT BASEMENT DOOR SEAL WEATHER STRIP AT THE TOP IS STUCK TO THE DOOR FRAME. Checked basement door seal weather strip on the left front (Road side) compartment door. Seal needs replaced. Pulled off old bulb seal. Used heat gun to remove double face tape. Cleaned off all sticky residue from seal mounting surface. Installed new bulb seal around flange of compartment door.	
66870	4	SCREWS COVERS ARE MISSING ON THE FACE OF THE STEPS THERE ARE 8 HOLES AND NOW THEY ARE MISSING SCREW COVERS ARE MISSING ON THE FACE OF THE STEPS. Checked steps going up to bedroom. (8) screw covers are missing. 3/31/2022: Turned in parts request for new wood screw covers to match step riser wood.	
66870	6	BED SLIDE HAS DAMAGED A DECAL ON THE LOWER RIGHT CORNER ON THE BODY BED SLIDE HAS DAMAGED A DECAL ON THE LOWER RIGHT CORNER ON THE BODY ABOVE COMPARTMENT DOOR. Checked decal. Decal was damaged by hard part of flange bulb seal on bedroom slide. Trimmed off bottom edge of bulb seal to remove hard part. 3/31/2022: Tored in parts request for a new decal.	

Claim : 66870

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
66870      2      THE WEATER STRIP ON BOTH LP DOORS ARE NOT LONG ENOUGH AND THEY
              KEEP SUCKING IN
              THE WEATHER STRIP ON BOTH LP DOORS ARE NOT LONG ENOUGH AND THEY
              KEEP SUCKING IN.
              Checked both LP compartment doors.  Foam seal that holds exterior
              panel to door frame is pulled out in corners.  Foam seal is too
              short and needs replaced.  3/31/2022:  Turned in parts for new
              foam seals.

66870      5      THE STEPS ARE SQUEAKING AND THE FLOOR FOR THE HALL WAY ALSO
              SQUEAKS CHEK AD ADVISE
              THE STEPS ARE SQUEAKING AND THE FLOOR FOR THE HALLWAY ALSO
              SQUEAKES.  CHECK AND ADVISE.
              Checked steps and floor at top of steps.  Tightened screws on
              steps.  Added shims for floor squeak between under side of floor
              and aluminum floor support.  Squeaks stopped.

66870      8      ON THE WALL ON THE BACK EDGE OF THE SHOWER THERE IS A GAP ABOUT
              1"
              ON THE WALL ON THE BACK EDGE OF THE SHOWER THERE IS A 1" GAP.
              Cut a piece of flat trim the length of shower wall.  Siliconed in
              place to cover 1 in. gap between shower surround and wall.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
221058        3      FOAM - TAPE -1/2"          15.00      0.37      5.55
639904        4      BUTTON-WOOD-3/8" M          8.00      0.16      1.28
653077        6      GRAPHIC                    1.00      8.65      8.65

```

```

*****
Lab Code     Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990         3      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         3      MISCELLANEOUS REPAIR          0.40     150.00     60.00
Z990         3      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         4      MISCELLANEOUS REPAIR          0.20     150.00     30.00
Z990         4      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         6      MISCELLANEOUS REPAIR          1.00     150.00    150.00
Z990         6      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         2      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         2      MISCELLANEOUS REPAIR          0.20     150.00     30.00
Z990         2      MISCELLANEOUS REPAIR          0.00     150.00      0.00
Z990         5      MISCELLANEOUS REPAIR          0.80     150.00    120.00
Z990         8      MISCELLANEOUS REPAIR          0.47     150.00     70.50
Z990         8      MISCELLANEOUS REPAIR          0.03     150.00      4.50

```

```

Parts Total:      15.48
Labour Total:     465.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 480.48

Customer Signature: _____

Date: _____

Claim : 66870

```
*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
```