

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13769B

Date In:	10 JUL 26	Author:	DLUCAS
Promised Date:	09 JUL 26	Stock No:	11364
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA CAMPING EDITION
:	CHICAGO, IL	Model:	283BHCE
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUTB7T4024686	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - all three of the          W    1021    FORES
          floor vents are cracked around the screw
          head
          CAUSE:      The heat duct covers in the living area
                      by the fridge and the one in front of
                      the bed have a crack from the screw
                      being tightened to much we will have to
                      order three new duct covers
          CORRECTION:  ..
WARR    COMPLAINT:  WARRANTY REPAIR 2 -the plastic corner        W    1021    FORES
          molding on the front t molding on the
          slide is bent out.  Corner block was
          installed too high.  Will need to
          replace t-molding due to exposed holes
          when corner block is lowered.
          CAUSE:      The corner plastic piece on the t
                      molding bent out from being mounted to
                      high up, if we moved it down it would
                      expose holes above it so we would need
                      to replace the whole piece of t-molding
          CORRECTION:  .
WARR    WARRANTY REPAIR 3 - Water pump is intermittent.          W    1021    FORES
          Sometimes it will turn on when opening a faucet,
          sometimes it will not turn on when opening a faucet.
WARR    WARRANTY REPAIR 4 - Customer states the entry door      W    1021    FORES
          lock cylinder on the handle portion will not turn
          with the key but the dead bolt works fine.
```

Continued on page 2

Work Order : 13769B

```
*****
Job # Part No   Description      PARTS      Bill to   Qty      Price      Total
*****
WARR0 822026546 REGISTER, GRILL, PLASTIC FL W-1021      0        2.81        0.00
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.00    140.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR EG  W-1021      0.00    140.00        0.00
ARR03 Z992      MISC LABOUR CODE (WARR      W-1021      0.00    140.00        0.00
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021      0.00    140.00        0.00
*****
```

```
*****
Job #  Excode   Description      EXTRAS      bill to   Qty      Price      Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021      1.00        0.00        0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
Totals            0.00        0.00        0.00        0.00        0.00        0.00
*****
```

&k2S
&k0S