

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13769B

Date In:	10 JUL 26	Author:	DMCGINLEY
Promised Date:	09 JUL 26	Stock No:	11364
:	:	Year:	2026
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA CAMPING EDITION
:	CHICAGO, IL	Model:	283BHCE
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUTB7T4024686	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - all three of the      W    1021    FORES
        floor vents are cracked around the screw
        head
        CAUSE:      The heat duct covers in the living area
        by the fridge and the one in front of
        the bed have a crack from the screw
        being tightened to much we will have to
        order three new duct covers
        CORRECTION:  REPLACE 3 DUCT COVERS  REQUEST 0.75
WARR    COMPLAINT:  WARRANTY REPAIR 2 -the plastic corner      W    1021    FORES
        molding on the front t molding on the
        slide is bent out.  Corner block was
        installed too high.  Will need to
        replace t-molding due to exposed holes
        when corner block is lowered.
        CAUSE:      The corner plastic piece on the t
        molding bent out from being mounted to
        high up, if we moved it down it would
        expose holes above it so we would need
        to replace the whole piece of t-molding
        CORRECTION:  REPLACE T MOLDING REQUEST 1 HOUR
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Water pump is          W    1021    FORES
        intermittent.  Sometimes it will turn on
        when opening a faucet, sometimes it will
        not turn on when opening a faucet.
        CAUSE:      BAD PUMP
        CORRECTION:  NEED NEW PUMP REQUEST 0.80
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Customer states the  W    1021    FORES
```

Continued on page 2

Work Order : 13769B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                entry door lock cylinder on the handle
                                portion will not turn with the key but
                                the dead bolt works fine.
CAUSE:      UNKNOWN
CORRECTION: REQUESTING 1 HOUR DIAG

```

```

*****
Job # Part No   Description        PARTS          Bill to   Qty    Price    Total
*****
WARR0 822026546 REGISTER, GRILL, PLASTIC FL W-1021      0      2.81     0.00

```

```

*****
Job#  Lab Code  Description        LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.00   140.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR EG   W-1021    0.00   140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR      W-1021    0.00   140.00    0.00
ARR03 RV9-24b   WATER PUMP R&R RVDA WA      W-1021    0.00   140.00    0.00
ARR02 TMOLD     T MOLDING R & R ON SLI      W-1021    0.00   140.00    0.00
ARR01 E845      VENT, FURNACE, R & R        W-1021    0.00   140.00    0.00

```

```

*****
Job #  Excode   Description        EXTRAS          bill to    Qty    Price    Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
Totals            0.00     0.00     0.00     0.00     0.00     0.00

```

&k2S
&k0S