

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13934

|                 |                     |                 |                   |
|-----------------|---------------------|-----------------|-------------------|
| Date In:        | 10 AUG 26           | Author:         | DMCGINLEY         |
| Promised Date:  | 20 AUG 26           | Stock No:       | 11107             |
| :               | :                   | Year:           | 2024              |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER      |
| Address:        | 21815 NETWORK PLACE | Brand:          | PUMA TT           |
| :               | CHICAGO, IL         | Model:          | 25BHS             |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      | 0                 |
| Phone#(res):    | 219-534-3167        | Exterior Color: | :                 |
| Phone#(bus):    | 219-534-3167        | Unit Type:      | TT-TRAVEL TRAILER |
| Cell Phone:     | :                   | License#:       | :                 |
| Email:          | NONE                | Tag#:           | :                 |
| Purchased Date: | 24 MAY 25           | :               | :                 |
| Delivery Date:  | 05 JUN 25           | :               | :                 |
| InService Date: | :                   | :               | :                 |
| Serial#:        | 5ZT2PUPB6R4020714   | :               | :                 |

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WHEN PUTTING THE AWNING IN, THE LEFT      E      R66      Route
          SIDE IS SLOWER THAN THE RIGHT AND GOES
          IN CROOKED
          CAUSE:      The fabric moved.  I took the set screws
          out moved the fabric over, put one set
          screw in place, ran the awning all the
          way out and back in and its still
          hanging up a little bit on the rear arm.
          The top of the arm is rubbing on the
          plastic head so i ran the awning back
          out, tapped the arm with a rubber
          mallet, ran the arm back in and the arm
          is closing properly.
          CORRECTION: Done.
WARR    COMPLAINT:  WHERE THE AWNING MEETS THE CAMPER THERE  E      R66      Route
          IS WATER RUNNING ON TO THE SIDE OF THE
          CAMPER (OFF THE AWNING) BY THE WINDOW
          WITH THE TABLE. NO LEAKS IN UNIT AS OF
          NOW.
          CAUSE:      Leak at the seam.  I sprayed the fabric
          with water and a drip started at the
          seam. I dried and cleaned the area and
          sealed around the seam on the top and
          bottom of the track. After the sealant
          dried i sprayed it with water again and
          the leak moved to a different spot. I
          cleaned and resealed along the whole
          length of the awning track.
```

Continued on page 2

Work Order : 13934

\*\*\*\*\*

| Job # | Description | JOB INFORMATION | Type | Bill To |
|-------|-------------|-----------------|------|---------|
|-------|-------------|-----------------|------|---------|

\*\*\*\*\*

CORRECTION: Done.

|      |            |                       |   |      |       |
|------|------------|-----------------------|---|------|-------|
| WARR | COMPLAINT: | AC NOT WORKING AT ALL | W | 1021 | FORES |
|------|------------|-----------------------|---|------|-------|

CAUSE: The a/c is low on coolant and needs replacement. I turned the a/c on and after 20 minutes the air coming out of the ducts is at 80 degrees. I pulled the assembly down and opened up the control box. I did an amp draw on the compressor wire and its at 06.50 amps. I tested the incoming and outgoing voltage and there is 110 and 12 volts. The whole a/c will have to be replaced because this style t-stat and control board are not compatible with the new units.

CORRECTION: ...

\*\*\*\*\*

| Job# | Lab Code | Description | LABOUR | Mech | Bill to | Hrs | Rate | Total |
|------|----------|-------------|--------|------|---------|-----|------|-------|
|------|----------|-------------|--------|------|---------|-----|------|-------|

\*\*\*\*\*

|       |      |                        |     |        |  |      |        |        |
|-------|------|------------------------|-----|--------|--|------|--------|--------|
| WARR  | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.38 | 140.00 | 53.20  |
| WARR2 | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.00 | 140.00 | 0.00   |
| WARR3 | DIAG | DIAGNOSTICS            | JGK | W-1021 |  | 1.00 | 140.00 | 140.00 |
| WARR  | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.00 | 140.00 | 0.00   |
| WARR2 | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.00 | 140.00 | 0.00   |
| WARR3 | DIAG | DIAGNOSTICS            | JGK | W-1021 |  | 0.00 | 140.00 | 0.00   |
| WARR  | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.62 | 140.00 | 86.80  |
| WARR2 | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 1.00 | 140.00 | 140.00 |
| WARR2 | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.00 | 140.00 | 0.00   |
| WARR2 | DIAG | DIAGNOSTICS            | JGK | E-R66  |  | 0.00 | 140.00 | 0.00   |
| WARR3 | A140 | AIR CONDITIONER, R & R |     | W-1021 |  | 0.00 | 140.00 | 0.00   |

\*\*\*\*\*

| Job # | Excode | Description | EXTRAS | bill to | Qty | Price | Total |
|-------|--------|-------------|--------|---------|-----|-------|-------|
|-------|--------|-------------|--------|---------|-----|-------|-------|

\*\*\*\*\*

|      |     |                          |       |  |      |       |       |
|------|-----|--------------------------|-------|--|------|-------|-------|
| WARR | SSE | SHOP SUPPLIES - EXTERNAL | E-R66 |  | 1.00 | 21.00 | 21.00 |
|------|-----|--------------------------|-------|--|------|-------|-------|

\*\*\*\*\*

## BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax | Total |
|------|---------|-------|--------|--------|--------|-----|-------|
|------|---------|-------|--------|--------|--------|-----|-------|

\*\*\*\*\*

|   |      |      |        |      |       |       |        |
|---|------|------|--------|------|-------|-------|--------|
| E | R66  | 0.00 | 280.00 | 0.00 | 21.00 | 16.57 | 317.57 |
| W | 1021 | 0.00 | 140.00 | 0.00 | 0.00  | 0.00  | 140.00 |

|        |  |      |        |      |       |       |        |
|--------|--|------|--------|------|-------|-------|--------|
| Totals |  | 0.00 | 420.00 | 0.00 | 21.00 | 16.57 | 457.57 |
|--------|--|------|--------|------|-------|-------|--------|

&amp;k2S

&amp;k0S