



Warranty Authorization Form

Date: 8/18/2026

General Information

Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Ph. 715-325-5170
mail@greenwayrv.com

Pre-Auth #: 972678

Unit: 573FR3025V3356574

Series: Reflection

Model: RF250ML-2027

Notes: RJ 08/18/2026 line 680026-denied nothing noted on the DAF (REQUIRED)
A copy of the complete, POST repair, customer-signed work order MUST be
provided with submitted claim.

Status: Approved with Modifications

Dealer Information

1127 Greenway RV Sales & Service
715-325-5170
mail@greenwayrv.com

Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Requestor: iclaim services
Return Fax #: (715) 325-5577
Email: greenway@dealer-advisors.com

Operation Line 1

Flat Rate Code: 580018 Slider/Crank Out Windows - Seal *Fault Code:* Improper Installation/Build
Glass

Serial #:

Model #:

Notes:

Problem: Customer states that they found a water leak under the window in the slide out. Later during the rainstorm, the water leak was apparent above the window. The customer found the Eterna bond tape on the roof of the slide to t-molding is not adheared well and suspects this as the entry point.

Time Requested: 1

Time Allowed: .75

Sublet Repairs: 0.00

Cause: The seal on the window is not long enough as shown in the pictures which is letting water come in during heavy rain.

Remedy: Need to clean and re-seal the window.

Status: Approved with Modifications

Operation Line 2

Flat Rate Code: 680026 Sofa - All - R&R Sofa/Theater Seat *Fault Code:* Damaged/Maintenance

Serial #:

Model #:

Notes:

Problem: Plastic on left recliner towards bottom has a "slice" in it.

Time Requested: 1

Cause: Plastic on left recliner towards the bottom has a slide in it.

Time Allowed: 0

Remedy: Replace recliner section.

Sublet Repairs: 0.00

Status: Denied

Denial Code: 11 - Not a Covered Repair

Operation Line 3

Flat Rate Code: 560052 Lg. Comp./Pass Thru/Kitch./Ent. Ctr. - *Fault Code:* Improper Installation/Build
R&R Seal

Serial #:

Model #:

Notes:

Problem: Front compartment caulk by water inlets is not done properly.

Time Requested: .4

Cause: The caulking around the front compartment, water inlet does not look like the sealant adhered very well.

Time Allowed: .4

Remedy: Will need to be taken off, cleaned and resealed.

Sublet Repairs: 0.00

Status: Approved