



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27609



WO #: 27609

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11365

Stock Desc: 2027 TT KZ-RV SPORTSMEN 383DBK

Model: 383DBK

Serial #: 4EZTS4029V5085025

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: BEDROOM SLIDING DOOR IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA

LABOR .10

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BEDROOM COUNTER IS SCRATCHED IN DIFFERENT PLACES ON TOP

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COUNTER TOP

LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: BEDROOM WALL HAS A BROWN STAIN ON IT

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA IF NEEDED

LABOR .10

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: TOP PIECE OF THE KITCHEN TABLE SEATING IS DAMAGED AND HAS HOLES IN THE FABRIC

CAUSE: NOTED ON DAF

CORRECTION: REPLACE TOP UPP PIECE OF KITCHEN SEATING

LABOR .50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: FRONT OF STOVE IS SRATCHED ON BLACK METAL AND ON THE SIDE SILVER PIECE AS WELL

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE GLASS STOVER TOP TO CORRECT THE BLACK PIECE DAMAGED. FOR THE SILVER AREA SCRATCHED POLISH AND BUFF. NOTE FOR FUTURE CUST THIS WAS DAMAGED ON DAF.
LABOR FOR BOTH REPAIRS TO STOVE 1.2

Subtotal for Job #5: 0.00**Job #6 - Warranty**

COMPLAINT: TRAY ON FRIDGE DOOR IS BROKEN

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE FRIDGE DOOR TRAY
LABOR .20

Subtotal for Job #6: 0.00**Job #7 - Warranty**

COMPLAINT: NDS MIDDLE LONG COMPARTMENT DOOR DROPS DOWN WHEN YOU OPEN IT A LITTLE. DOOR WILL NOT CLOSE CORRECTLY. YOU HAVE TO PICK UP ON THE DOOR TO GET IT TO SHUT.

CAUSE: NOTED ON DAF
DEFAULT IN DOOR

CORRECTION: REPLACE COMPARTMENT DOOR
LABOR .50

Subtotal for Job #7: 0.00**Job #8 - Warranty**

COMPLAINT: DS OF THE UNIT HAS DAMAGE TO BOTH CENTER HUB COVERS

CAUSE: NOTED ON DAF
UNIT ARRIVED AT DEALER WITH THIS ISSUE

CORRECTION: REPLACE BOTH CENTER HIB COVERS
WILL NEED TO REPACK THE BEARING ON BOTH WHEELS WHEN REPLACING THESE AS WELL.
LABOR FOR REPAIRS 2.0

Subtotal for Job #8: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Aug 2026

W/O: 27609



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

