



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27450



WO #: 27450 (Appointment Date: 22 JUL 2026 - Time: 10:00am)

Customer: 93780 - WOODS, SHANNON
Address: 6202 SILVER FOX TRAIL
MORRISTOWN, TN
37814

Home Phone: 423-539-9468

Work Phone:

Author: SPD

Location: IH

Invoice #:

Stock #: 11178

Stock Desc: (11178) 2026 FOREST RIVER

ROCKWOOD GEO 20FBS

Model: 20FBS

Serial #: 5ZT2RSKC5T3039136

Chassis #:

Mileage:

Key #:

Req'n #: 62957

License #:

Trim: G20FBS

Purchase Date: 13 MAR 26

Date In: 15 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 12 AUG 26

Warr. Date: 13 MAR 26

Job #1 - Warranty

COMPLAINT: FRONT SHADE IS NOT WORKING PROPERLY CUST KEEPS PUTTING THE END CAP ON SHADE AND THE BAR AT THE BOTTOM IS SLIDING CHECK AND ADVISE

CAUSE: END CAP WILL NOT STAY ON THE SHADE. THE BOTTOM BAR ON SHADE IS MOVING AND THIS HAS CAUSED THE FABRIC TO WRINKLE.
DEFECT IN THE SHADE.

CORRECTION: REPLACE THE SHADE
LABOR .40

Labor

Job #	Description	Hours	Total
1	REPLACED SHADE	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100596330	SHADE - PFL: ROLLER NIGHT SHADE - BLACK - 39" X 24" - V# FRNB39X24RS X	1.00	52.13	52.13

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
FRT	FREIGHT ON PARTS	1.00	5.00	5.00

Subtotal for Job #1: 92.13

Job #2 - Warranty

COMPLAINT: FRONT STABILIZER JACK ON DOOR SIDE IS INOP CHECK AND ADVISE

CAUSE: VERIFIED THE FRONT RIGHT STABILIZER JACK HAS HOLES THAT ARE RIPPED BETWEEN LOCKING HOLES.

CORRECTION: NEED TO REPLACE THE STABILIZER ASSEMBLY
LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED INNER LEG	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 93780
WOODS, SHANNON



F100461615	STABILIZER JACK PART - 2E-3: PAWL AND LEG REPLACEMENT KIT	1.00	33.33	33.33
------------	--	------	-------	-------

Subtotal for Job #2: 120.83

Job #3 - Warranty

COMPLAINT: GAS TANK COVER IS BROKEN CHECK AND ADVISE

CAUSE: VERIFIED THE LP TANK COVER HAS DEVELOPED A CRACK

CORRECTION: REPLACE THE LP TANK COVER

LABOR .50

Labor

Job #	Description	Hours	Total
3	REPLACED LP TANK COVER	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
F100395460	LP TANK COVER PFL DOUBLE COVER FOR 20 LB TANKS BLACK	1.00	28.78	28.78

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	78.25	78.25

Subtotal for Job #3: 124.53

Job #4 - Warranty

COMPLAINT: ODS MARKER LIGHT IN REAR IS INOP CHECK AND ADVISE

CAUSE: VERIFIED THE LEFT SIDE BOTTOM REAR LIGHT IS NOT ILLUMINATING WITH THE REST. PHOTOS ARE ATTACHED SHOWING ALL THE OTHER LIGHTS ARE ON AND WORKING EXCEPT REAR LEFT.

CORRECTION: REPLACE THE REAR LEFT MARKER LIGHT (RED)

LABOR .40

Labor

Job #	Description	Hours	Total
4	REPLACED REAR LEFT MARKER LIGHT	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100069327	LIGHT - 3D-2: LED CLEARANCE LIGHT, W/ GASKET, OVAL - RED LENS/BLACK BASE	1.00	1.74	1.74

Subtotal for Job #4: 36.74

Parts Total:	115.98
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	83.25
WORK ORDER TOTAL:	374.23

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

W/O: 27450



Customer #: 93780
WOODS, SHANNON



Customer Signature : _____

Date: 12 Aug 2026

W/O: 27450



Customer #: 93780
WOODS, SHANNON



Customer Work
Order

