



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27620



WO #: 27620

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11369

Stock Desc: 2027 TT FOREST RIVER

ROCKWOOD MINI 2524FBT

Model: 2524FBT

Serial #: 4X4TRLB26VD470983

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 24 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: FLAT TIRE ON NDS OF UNIT

CAUSE: NOTED ON DAF

CORRECTION: TECH PUT AIR UP TO 65 AND WITHIN A FEW MIN IT HAD ALREADY DROPPED TO 50. TECH TOOK TIRE OFF AND THERE IS NO SIGN OF ANYTHING IN THE TIRE AND WE DONE THE SOAPY WATER TEST WITH NO RESULTS OF LEAKING AIR. FAULTY TIRE
LABOR TO REPLACE TIRE TIRE AND DIAG 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE BOTTOM METAL STRIP ON THE BOTTOM OF THE SHADE IS DAMAGED AND HAD A PLACE WHERE IT DENTS IN AND SILVER COLOR COMING THROUGH

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SHADE
LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: HIDDEN CABINET ABOVE THE FIREPLACE IS HITTING THE COUNTER TOP WHEN FOLDING OPEN

CAUSE: NOTED ON DAF

CORRECTION: NEED TO REMOVE THE COMPLETE FOLD OUT TOP AND ADJUST TO OPERATE WITH OUT HITTING THE COUNTER. SECURE THE DRAWER GUIDE IN AS WELL
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: EXTERIOR ENTRY DOOR HAS NICS AND A SMALL AREA OF THE PAINT MISSING

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH AREA, TOUCH UP WITH PAINT AND BLEND AREA

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .30

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BATHROOM DOOR IS HITTING THE WALL WHEN YOU GO TO SLIDE IT BACK TO EXIT THE BATHROOM. THIS HAS CAUSED A SMALL SCRATCH ON THE DOOR AND ALLOWING THE ROUND DOOR HANDLE INSERT TO PULL OFF DOOR.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE DOOR AND ADJUST THE TRACK/DOOR ON TRACK TO SLIDE BACK WITHOUT HITTING THE WALL AND CAUSING DAMAGE TO THE DOOR.
LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED ON RIGHT SIDE GOING UP INTO THE UNIT. THERE IS DIFFERENT SIZE SCRATCHES IN A COUPLE DIFFERENT LOCATIONS ON THESE STEPS.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, PAINT AND BLEND AREA TO MATCH
LABOR .40

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: AWNING FABRIC HAS A AREA THAT HAS 2 INDENTIONS ON IT RIGHT IN THE MIDDLE OF THE FABRIC AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE AWNING FABRIC
LABOR 1.0

Subtotal for Job #7: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 24 Aug 2026

W/O: 27620



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

