



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73090-1
Promised Date:
04 AUG 26



WO #: 73090-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 19 AUG 26

Invoice#:

Author: ADVISOR

Stock Desc: 9689 2026 TRACER 275BH

Serial#: 527080

Chassis#: 5ZT2TRTB4TB527080

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 05 MAY 26

Time In:

Job #01 - Warranty

COMPLAINT: Transferred to RV*73090-2 on 16 JUN 26

Estimate amount was 0.00

Wire short for awning

CAUSE: Wire short from factory

CORRECTION: The shorted wire have to found behind the wall of the unit. It can cause a fire inside. Tech has to unscrew the compartments in the kitchen and besides the door opening. The fuse box has to be unscrewed and removed so the wires can be found. Once found the new wires need to be run back through the walls and connected to correctly to the fuse box and to the switch of the awning. All screws and compartments need to be replaced back to the factory location and installed. The awning wires also are attached to the lights of the unit.

Request 8 hours

Photos attached

Labor

Job #	Description	Total
01	Wire short for awning(WARRANTY)	0.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	0.00	0.00

Subtotal for Job #01: 0.00

Job #03 - Warranty

COMPLAINT: Transferred to RV*73090-2 on 16 JUN 26

Estimate amount was 0.00

DAMAGE TO SIDE FACIA CABINET OVER SINK

CAUSE: Factory bad install

CORRECTION: Tech has to unscrew damaged facia remove. Also unscrew cabinet, remove cabinet for repair over the kitchen sink. Once parts are in the facia has to be replaced and screwed back in. The kitchen cabinet has to be screwed and replaced back into factory location.

Request 4 hours

Labor

Job #	Description	Total
03	Damaged fascia (WARRANTY)	0.00

Customer #: 1000
MYERS "RV" CENTER,
INC.,



Subtotal for Job #03: 0.00

Job #04 - Warranty

COMPLAINT: TV HAS SCRATCHES

CAUSE: Bad install
Replace tv

CORRECTION: Tv need to be unscrewed and then replaced with a new TV. New tv needs to be screwed back in to tv and placed back into fatory position. The new tv has to tested and made sure it's working.
Request 1.5 hours
Done

Labor

Job #	Description	Total
04	MULTIPLE LABOR CODES	95.00

Parts

Part #	Description	Qty	Price	Total
4911	BATTERY AAA	2.00	0.69	1.38
F100755440	TV - LED FIRE, REMOTE NS-50F501NA26 - INSIGNIA 50"	1.00	403.37	403.37

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	158.62	158.62

Subtotal for Job #04: 658.37

Job #05 - Warranty

COMPLAINT: SCRATCHES ON STOVE TOP COVER

CAUSE: Unknown
Replace stove top glass

CORRECTION: Stove top needs to be unscrewed and taken off. A new replacement needs new screws and stove top needs to be screwed back into fatory location. Then the stove needs to be tested for leaks.
Request 1.5
Done

Labor

Job #	Description	Total
05	STOVE TOP GLASS	19.00

Parts

Part #	Description	Qty	Price	Total
F100837375	GLASS COVER (ONLY) FOR COOKTOP CT-1700BKTC	1.00	56.90	56.90

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	69.66	69.66

Subtotal for Job #05: 145.56

Job #A - Warranty

COMPLAINT: Transferred to RV*73090-2 on 16 JUN 26
Estimate amount was 0.00
Awning electrical short

CAUSE: ELECTIRCAL SHORT

CORRECTION: Upon PDI and delivery awning was not working. The awning and internal lights were not

W/O: 73090-1
Promised Date: 21 AUG 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 73090-1
Promised Date: 21 AUG 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



working, the fuse was blown. The awning and internal lights are connected to the same fuse. Tech opened the awning manually and disconnected the power plug and tested the power wire at that time the awning did retract and open. Tech then followed the awning wires to the wall outside wall of the entrance of the inside of the unit, the wires of the awning did work there is no pinched wires. The tech found that there is a short inside of the RV unit and still needs to find the short. This short not only affects the awning but the interior lights as well. Tech needs more time to find the short to ground wires inside of the RV unit. Tech has spent 4 hour on unit now.

Request 8 hours

Photos attached

Labor

Job #	Description	Total
A	MISC LABOUR CODE (WARRANTY)	0.00

Subtotal for Job #A: 0.00

Parts Total: 461.65
Labour Total: 114.00
Sublet Total: 0.00
Extras Total: 228.28

WORK ORDER TOTAL: 803.93

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Aug 2026

