

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106

BASDEN RV CENTER INC

DBA AMERICAN RV CENTER

600 E BASELINE ROAD

EVANSVILLE, IN 47725

USA

CLAIM STATUS

CLAIM

Authorized
1102147

CLAIM ORIGIN

WEB

ORIGINAL CLAIM ID

VIN

5ZT2CANB1MU039158

CHASSIS VIN

MILEAGE

0

SITE/WAREHOUSE

103 / 103

ITEM #

CAT243RBSLE

DEALER RO #

67755

CLAIM START DATE

06/20/2022

CLAIM END DATE

01/01/1900

Labor rate: \$150.00

OWNER INFORMATION

TOM GARRETT

1345 WESTWIND DR

Avon, IN 46123

USA

Retail Date of Purchase 06/22/2021

WARRANTY EXPIRATION DATE

06/22/2022

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/ No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-06-20 09:13:58 :: SLIDE SEALS ARE DAMAGED
Checked slide flap seals. Flap seal torn at top rear corner of slide. Flap seals top and sides are glued
together at top. All three sides need to be replaced. 6/20/2022: Turned in parts request for new flap and
bulb seals. 30 ft. of each. Additional Note : bhoffman@americanrvcenter.com, 2022-06-20 09:23:35 :: AFTER
INSPECTION WE FOUND THAT THE ROOM NEEDS TO BE ADJUSTED AND TRIM SO THIS DOES NOT
HAPPEN AGAIN

Model #

Dlr Sub Hrs

6.00

Sub Labor Amt \$900.00

Serial #

Appr Hrs

3.00

Appr Labor Amt \$450.00

Notes

ADDITIONAL PHOTOS ARE NEEDED IN ORDER TO JUSTIFY 6 HOURS OF LABOR.
WHAT PHOTOS DO YOU NEED ALL THE SEALS NEED TO BE REPLACED AND THE ROOM ADJUSTED
I WILL NEED TO SEE PHOTOS OF ALL THE SLIDE SEALS. HOW MANY ARE YOU REPLACING?
PHOTOS HAVE BEEN UPDATED
EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME OF 1 HR PER SIDE FOR BULB SEAL

Submitted	Labor Amt	\$900.00
	Parts & Freight	\$0.00
	Total	\$900.00

Approved	Labor Amt	\$450.00
	Parts & Freight	\$0.00
	Total	\$450.00

DEALER DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.