

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13633

Date In:	11 JUN 26	Author:	KOTT
Promised Date:	18 JUN 26	Stock No:	11422
:	:	Year:	2026
Customer Name:	18030 - KEMPF-NEMEC, S	Manufacturer:	FOREST RIVER
Address:	1514 WOODLAWN RD	Brand:	PUMA DESTINATION
:	WAUSAU, WI	Model:	429LFT
Postal/Zip:	54403	Miles/Hrs:	0
Phone#(res):	7152977101	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	715-571-1359	License#:	:
Email:	SNEMEC1514@GMAIL.COM	Tag#:	JENNA BO
Purchased Date:	10 APR 26	:	:
Delivery Date:	28 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPU822TP106946	:	:

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  CUSTOMER STATES THAT THE AWNING WAS IN      W      1021      FORES
                DURING THE RECENT STORMS THE AWNING WAS
                PUT IN- WHEN THEY WENT BACK OUT TO THE
                UNIT THE AWNING BOTTOM ARM BROKE AND
                NEEDS TO BE LOOKED OUT- CUSTOMER STATES
                THAT THEY HAD ONLY HAD THE AWNING AND IN
                AND OUT 3 TIMES- CUSTOMER STATES THAT
                THE BOLT BUSTED RIGHT AT THE ELBOW-
    CAUSE:      pics taken of tags for new awning arm
                what I found is the pivot arm was loose
                possibly got wedge in awning hardware
                will need complete awning arm fabric and
                tube seems ok and awning lights don't
                work as due to pinched 12 volt wiring
                between awning hardware
    CORRECTION: Will need a new awning arm and new
                awning light ....
2      CUSTOMER NEEDS A SERVICE CALL OUT TO LAKESIDE FIRE      E      18030      KEMPF
    CAMPGROUND SITE # 048
3      COMPLAINT:  CUSTOMER STATES SLIDING PATIO DOOR          W      1021      FORES
                DOESNT LOCK
    CAUSE:      pics taken What I found was the sliding
                door was getting caught on rubber guide
                grommet now allowing slider door to
                close completely I couldn't test the
                locking mechanism due to no key customer
                has
    CORRECTION: trimmed rubber grommet so that would
```

Continued on page 2

Work Order : 13633

```

*****
Job #      Description          JOB INFORMATION          Type Bill To
*****
              allow sliding door to close completely
              and  latch the door is now working

```

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to    Hrs    Rate    Total
*****
   1  WARR      MANUFACTURER WARRANTY  JS    W-1021      0.50   140.00    70.00
   3  WARR      MANUFACTURER WARRANTY  JS    W-1021      0.50   140.00    70.00

```

```

*****
Job #  Excode    Description    EXTRAS          bill to    Qty    Price    Total
*****
   2   SSE      SHOP SUPPLIES - EXTERNAL  E-18030    1.00     0.00     0.00
   2   SC       SERVICE CALL              E-18030    0.00     3.75     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021        0.00    140.00     0.00     0.00     0.00    140.00

          Totals        0.00    140.00     0.00     0.00     0.00    140.00

```

&k2S
&k0S