



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68
Promise Date: 25 JUN 22

CUSTOMER WORK ORDER

WO #: 68087

Customer: 44932 - SUTTON, DENNIS A.
- 812-646-1059

Tag:

Author: BH

Location: 0805 CHECK PARTS

Stock #: 10943

Stock Desc: 2022 TT COACHMEN

CATALINA 303RKDSLE

Chassis #: 5ZT2CAVB3NX024693

Serial #: 5ZT2CAVB3NX024693

Mileage:

Licence:

Invoice #:

Date In: 27 JUL 22

Promised: 25 JUN 22

Date Sched:

Completed: 29 JUL 22

Warr. Date: 19 MAY 22

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CORRECTION: verified that the quick connect was warranty then removed and replaced with new quick connect

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00

Subtotal for Job #22V243: 45.00

Job #2 - Internal

COMPLAINT: ALL THREE STORAGE COMPARTMENTS DOORS ARE VERY HARD TO LOCK AND UNLOCK.

CAUSE: CUSTOMER STATED DOORS WERE HARD TOP OPEN. THEY NPOEN FINE FOR USE. SPRAYED THEM WITH LUBRICANT

CORRECTION: SPRAYED WITH LUBRICANT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: THE LIGHT COVER IN THE MASTER BEDROOM NEAREST THE CLOSET IS DEFECTIVE.

CAUSE: LIGHT COVER IN BED ROOM WAS LOSE REATTACHED AND TESTED

CORRECTION: RE ATTACHED LIGHT AND TETSTED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THERE IS TRIM MISSING IN THE BOTTOM OF THE BEDROOM SLIDE.

CORRECTION: ONE PIECE OF TRIM WAS MISSING FOR TH J WRAP. PUT A NEW PIECE OF TRIM IN



Customer #: 44932
SUTTON, DENNIS A.

PLACE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Subtotal for Job #4: 60.00

Job #5 - Internal

COMPLAINT: THE RIGHT BRACKET ON THE BOTTOM KITCHEN DRAWER IS LOOSE.

CAUSE: RIGHT BRACKET ON BOTTOM KITCHEN DRAWER WAS LOSE DUE TO MISSING SCREW

CORRECTION: INSTALLED NEW SCREW TO BRACKET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #5: 0.00

Job #6 - Internal

COMPLAINT: THE CAMERA ANTENNA IS LOOSE.

CAUSE: CAMERA ANTENNA WAS NOT SCREWED ON PROPERLY

CORRECTION: SCREWED ON ANTENA PROPERLY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CHECK THE ELECTRICAL WIRING COVER NEAR THE END THAT PLUGS INTO THE TRUCK. THERE ARE WIRES SHOWING.

CORRECTION: PUT IN A PO FOR NEW 7 PIN TRAILER PLUG.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
19430	10' MOLDED 7-WAY CORD	1.00	50.54	50.54

Subtotal for Job #7: 125.54

Parts Total: 50.54
 Labour Total: 180.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 230.54

W/O: 68
 Promise date: 25 JUN 22

Customer #: 44932
 SUTTON, DENNIS A.