



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68197
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68197

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0923 BH TO CLOSE

Stock #: 11117
Stock Desc: 2023 TT COACHMEN
CATALINA 263BHCKLE
Chassis #: 5ZT2CARB0PU040963
Serial #: 5ZT2CARB0PU040963
Mileage: 0
Licence:

Invoice #:
Date In: 06 AUG 22
Promised: 31 AUG 22
Date Sched:
Completed: 26 SEP 22
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: 2 LIGHT COVERS FELL OFF

CAUSE: INSTALLED LIGHT COVERS. BOTH LIGHTS ARE VERY DIM. LIGHTS NEED REPLACED.

CORRECTION: INSTALLED LIGHT COVERS. WAITING ON APPROVAL FOR NEW LIGHTS 8/9/22

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: STAPLES NEED SET ON BEDROOM WALL

CAUSE: set staples on wall

CORRECTION: set staples and filled with putty

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00



Customer #: 1000
BASDEN'S AMERICAN RV,





Subtotal for Job #2: 30.00

Job #3 - Internal

COMPLAINT: STAPLES NEED SET ON BATHROOM CEILING

CAUSE: SET STAPLES ON CEILING

CORRECTION: SET STAPLES AND FILLED WITH PUTTY.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: BATHROOM LIGHT SWITCH PUSHING OUT

CAUSE: light switch is pushing out of the "cover plate"

CORRECTION: removed cover plate and switch from wall. pushed rear tabs out on switch and applied super glue to help hold in place. installed light switch and cover plate to wall.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00

Subtotal for Job #4: 30.00

Job #5 - Warranty

COMPLAINT: BEDROOM SCREEN DOOR LATCH CAME OFF

CAUSE: DOOR HAS A HOLE IN IT FROM FACTORY. THEY INSTALLED SCREEN DOOR LATCH AND MOVED IT. THEN PUT A LARGER SCREW IN TO HOLD IT. SCREW TORE THE INNER WALL OF THE DOOR. WAITING ON APPROVAL FOR NEW DOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	150.00

Parts

Part #	Description	Qty	Price	Total
F100113230	DOOR, ENTRY 26" X 71.50" FRICTION HINGE RH RADIUS CORNER 1/2"	1.00	402.63	402.63

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - ENTRY DOOR	1.00	146.99	146.99

Subtotal for Job #5: 714.62

Job #6 - Warranty

COMPLAINT: STAIN ON THE COUCH

CAUSE: STAIN ON COUCH CUSION

CORRECTION: REMOVED WITH MINERAL SPIRITS AND A RAG

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00





Subtotal for Job #6: 30.00

Job #7 - Warranty

COMPLAINT: SILVERWEAR DRAWER HARD TO CLOSE

CAUSE: drawer is hard to close.

CORRECTION: applied silicone lubricant to drawer guides.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00

Subtotal for Job #7: 30.00

Job #8 - Warranty

COMPLAINT: BACK WALL IS TWO DIFFERENT COLORS

CAUSE: TOOK PICS. BACK WALL WAS SPRAYED AT THE TOP DOWN TO THE MIDDLE OF THE WALL.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	300.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	600.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100336521	DECAL, 41" COACHMEN W/ PETE LEGEND (WHITE) 166866-01	1.00	10.71	10.71
F100337015	GRAPHIC, SD/RR CATA LEGEND 202529 2023	1.00	5.90	5.90
C01303901	METAL, .024 X 16" X 96" 1MDM SL COACHMEN GRAY 0241609601	1.00	52.27	52.27
6378	36" X 96" COACHMEN GREY METAL	1.00	117.53	117.53
20-6983	LONG LEG INSERT CORNER MOLDING- BLACK- 8 FT	2.00	24.41	48.82
500627	CLEAR SIKASIL PLUS	2.00	8.51	17.02
E369	E369 BLACK HD 1" x 25' INSERT TRIM	1.00	8.11	8.11
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	6.20	6.20

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - METAL	1.00	331.92	331.92

Subtotal for Job #8: 1,498.48

Job #10 - Warranty

COMPLAINT: 2 LED PUSH BUTTON LIGHT ARE NOT WORKING VERY DIM

CAUSE: TWO LEDS ARE DIM

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00



W/O: 68197
Promised Date: 31 AUG 22

Parts

Part #	Description	Qty	Price	Total
C01297663	4.5 INCH LED LIGHT PUCK BASE WITH LENS WHITE PUSH BUTTON SWITCH 0016274CW-H	2.00	3.38	6.76

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 8,10	1.00	15.90	15.90

Subtotal for Job #10: 52.66

Parts Total: 675.95
Labour Total: 1,215.00
Sublet Total: 0.00
Extras Total: 494.81
WORK ORDER TOTAL: 2,385.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Sep 2022



Customer #: 1000
BASDEN'S AMERICAN RV,

