

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1207104
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKEC9NY023069
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	017 / 017D
OWNER INFORMATION		ITEM #	CKTR16PF-D
FRANCIS T COOMES		DEALER RO #	68397
130 E NEW ALBANY AVE		CLAIM START DATE	08/26/2022
Vincennes, IN 47591		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/30/2022	WARRANTY EXPIRATION DATE	06/30/2023

Claim Line Details

Labor

Line# 1	Operation Code RC-026-05-00-004185	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - INSPECT ONLY - Recall/LP Gas System/Inspect/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2022-08-26 09:30:57 :: RECALL 22V243 LP QUICK CONNECT RECALL FOR LP QUICK DISCONNECT. LP QUICK DISCONNECT DIDNT MATCH REACLL SPECS NOI ACTION NEEDED	
	Model #	Dlr Sub Hrs 0.10
	Serial #	Appr Hrs 0.10
		Sub Labor Amt \$15.00
		Appr Labor Amt \$15.00
	Notes	

Labor

Line# 2	Operation Code RC-042-15-00-004215	Operational Description 22V556, 2022-368 - LCI AWNINGS 20E-055 - INSPECTION, REPAIR OR REPLACEMENT ONLY - Recall/Awning/Repair or Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2022-08-26 09:34:54 :: RECALL 22V556 LCI AWNING COMES DETACHED RECALL FOR AWNING G. AWNING MET DATES AND HAS A SPLIT IN SEAM LESS THEN 6 INCHS AND NEEDED REPIRED USED REPIRED KIT AND USED ADHESSIVE TO FIX SEAM	
	Model #	Dlr Sub Hrs 0.20
	Serial #	Appr Hrs 1.50
		Sub Labor Amt \$30.00
		Appr Labor Amt \$225.00
	Notes	
	Authorized	

Submitted	Labor Amt	\$45.00	Approved	Labor Amt	\$240.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$45.00		Total	\$240.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.