



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27797



WO #: 27797

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11387

Stock Desc: 2027 TT KEYSTONE BULLET 26BHC

Model: 26BHC

Serial #: 4YDTBLM27VD430366

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 06 OCT 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HAS A SMALL CHIP ,SCRATCHED AT BOTTOM AND CHIPS.

CAUSE: DAMAGED AT INSTALL.

NOTED ON DAF

CORRECTION: REPLACE BATHROOM DOOR

LABOR .40

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE METAL PIECE THAT IS BETWEEN THE BUNK BEDS IS SCRATCHED AND DAMAGED IN SEVERAL AREAS.

CAUSE: SCRATCHED AT INSTALL,NOTED ON DAF.

CORRECTION: REMOVE AND REPLACE THE ALUMINIUM BAR BETWEEN THE BUNK BEDS.

LABOR .75

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: THE SLIDE STILE BOARD HAS A VERY DEEP SCRATCH ON THE RIGHT SIDE IF FACING IT.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE WITH NEW STILE

LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: BEDROOM SLIDING DOOR IS CHIPPED AND HAS DAMAGE IN SEVERAL AREAS THROUGHOUT THE DOOR.

CAUSE: NOTED ON DAF,DAMAGED AT FACTORY BUILD.

CORRECTION: REMOVE DAMAGED DOOR AND REPLACE WITH NEW ONE

LABOR .50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #6: 0.00**Job #7 - Warranty**

COMPLAINT: THE BEDROOM DOORS HAVE A BIG GAP AT THE TOP WHEN CLOSED COMPARED TO THE BOTTOM.

CAUSE: NOTED ON DAF

CORRECTION: DOORS NEED TO BE ALIGNED TO CLOSE PROPERLY.

LABOR .40

Subtotal for Job #7: 0.00**Job #8 - Warranty**

COMPLAINT: LIGHT ON THE CEILING IN THE BEDROOM IS VERY LOOSE AND HARD TO TURN ON.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE CEILING LIGHT

LABOR .40

Subtotal for Job #8: 0.00**Job #9 - Warranty**

COMPLAINT: THE CEILING LIGHT AT THE ENTRY OF THE UNIT IS MISSING THE COVER

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE CEILING LIGHT COVER

LABOR .20

Subtotal for Job #9: 0.00**Job #10 - Warranty**

COMPLAINT: INTERIOR KITCHEN TABLE PEDESTALS ARE MISSING. UNIT HAS BEEN LOOKED OVER AND CHECKED IN ALL AREAS.

CAUSE: NOTED ON DAF.

CORRECTION: REPLACE BOTH TABLE PEDESTALS

LABOR .40

Subtotal for Job #10: 0.00**Job #11 - Warranty**

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED ON THE THRESHOLD.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE ENTRY DOOR STEPS

LABOR 1.0

Subtotal for Job #11: 0.00

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



W/O: 27797

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 07 Oct 2026

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

