

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1284529
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAZB5NX025726
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT343BHTSLE
JOSHUA D. JOHNSON		DEALER RO #	68947
2703 E 600 S		CLAIM START DATE	10/19/2022
Fort Branch, IN 47648		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/07/2022	WARRANTY EXPIRATION DATE	05/07/2023

Claim Line Details

Labor

Line# 1	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-19 13:33:07 :: OUT DOOR KITCHEN IS LEAKING, POSSIBLY COMING FROM UNDER THE SINK. CHECK FOR DAMAGE BRING UNIT IN OFF OF LOT, WATER TEST FOR LEAKS, FOUND FITTINGS FOR WATER LINES TO FAUSET UNDER SINK LEAKING, GET NEW CONE WASHERS AND REPLACE, WATER TEST, MAESURE WOOD FOR PO SHEET AND TURN IN PO, BOTTOM OF FACE FRAM HAS WATER DAMAGE WILL HAVE TO FI THE WOOD DAMAGE	
	Model #	Dlr Sub Hrs 0.20 Sub Labor Amt \$30.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$30.00
	Notes AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 20-46-02-00-000721	Operational Description Window - Exterior/Windows/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-19 13:34:36 :: WHEN DRIVING, THE DOOR SIDE FRONT WINDOW DOES NOT SEEM TO LATCH WINDOW NOT CLOSING ALL THE WAY, WILL NOT LATCH CHECK WINDOW, OUT SIDE IS 30 1/4 IN BY 23 1/4IN INSIDE FOR CUT OUT IS 29 3/4 IN BY 21 3/4 IN TURN PO FOR WINDOW	
	Model #	Dlr Sub Hrs 0.20 Sub Labor Amt \$30.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$30.00
	Notes	

Labor

Line# 3	Operation Code 20-58-01-00-000608	Operational Description Metal - Aluminum Siding, each - Exterior/Metal, Aluminum Siding/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-19 13:45:41 :: FRONT DOOR SIDE COMPARTMENT METAL SEEMS TO FLEX WHEN DRIVING RIGHT ABOVE THE MAGNET. FOUND UNIT ABOUT THE COMPARTMENT DOOR THE METAL IS LOOSE AND THE STAPLES HAVE COME UNDONE WILL HAVE TO REMOVE THE CORNER TRIM AWNING WINDOW AND DOOR TO FIX THE METAL	
	Model #	Dlr Sub Hrs 7.00 Sub Labor Amt \$1,050.00
	Serial #	Appr Hrs 7.00 Appr Labor Amt \$1,050.00

Labor
Line# 4

Notes
AUTHORIZED AS REQUESTED

Operation Code
30-100-01-00-001050

Operational Description
Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-10-19 13:53:04 :: FIX DAMAGE FROM THE WATER LEAK MAESURE WOOD FOR PO SHEET AND TURN IN PO, BOTTOM OF FACE FRAME HAS WATER DAMAGE WILL HAVE TO REMOVE ALL THE DAMGED WOOD AND INSTALL NEW

Model #	Dlr Sub Hrs	3.00	Sub Labor Amt	\$450.00
Serial #	Appr Hrs	3.00	Appr Labor Amt	\$450.00

Notes
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$1,560.00
	Parts & Freight	\$0.00
	Total	\$1,560.00

Approved	Labor Amt	\$1,560.00
	Parts & Freight	\$0.00
	Total	\$1,560.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.